

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 1081 D

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT WISHBONE LINK-RH ? <i>xan</i>	\$	507.00
22	FRONT SUSPENSION GUIDE-RH ? <i>xan</i>	\$	887.00
23	FRONT UPPER CONTROL ARM-RH ? <i>xan</i>	\$	480.00
24	FRONT UPPER CONTROL ARM-RH REAR ? <i>xan</i>	\$	480.00
25	FRONT WHEEL HOUSING BEARING-RH ? <i>xan</i>	\$	912.00
26	FRONT SWIVEL JOINT-RH ? <i>xan</i>	\$	192.00
27	FRONT WHEEL HUB-RH ? <i>xan</i>	\$	460.00
28	FRONT WHEEL BEARING KIT ? <i>xan</i>	\$	237.00
29	FRONT SUSPENSION FORK-RH ? <i>xan</i>	\$	249.00
30	FRONT COUPLING ROD ? <i>xan</i>	\$	125.00
31	FRONT DRIVESHAFT <i>xan</i>	\$	2,498.00
32	FRONT GAS SHOCK ABSORBER-RH ? <i>xan</i>	\$	284.00
33	FRONT TRACK ROD ? <i>xan</i>	\$	93.00
34	FRONT TRACK ROD CLAMP ? <i>xan</i>	\$	6.00
35	FRONT TRACK ROD SPRING BAND CLAMP ? <i>xan</i>	\$	42.00
36	FRONT TIE ROD END ? <i>xan</i>	\$	186.00
37	SUNDRIES ? <i>for use</i>	\$	400.00 2-56

TOTAL SPARE PARTS CHARGES

: \$ 20,142.00

TOTAL LABOUR CHARGES

: \$ 8,242.00

GRAND TOTAL

: \$ 28,384.00

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 1081 D

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	phh? /
2	To remove and renew rhs front wheel suspension assy.	S/N \$ 1,800.00	? Xnn
3	^R To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organsie crash management components. Reinstall all parts removed.	\$ 2,450.00	1000 /
4	To respray front bumper, rhs front fender and bonnet.	\$ 2,800.00	1100 /
5	To carry out pre-wheel alignment and post-wheel alignment. To renew rhs front rim.	S/N \$ 520.00	report? /
6	To carry out diagnostic check.	S/N \$ 192.00	/ /
TOTAL LABOUR CHARGES		:	<u><u>\$ 8,242.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 1081 D

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>repair cm</i>	\$	2,068.00 <i>1736.80</i>
2	FRONT BUMPER FIXING PARTS <i>X su</i>	\$	269.00
3	FRONT BUMPER SECURING STRIP <i>X su</i>	\$	34.00
4	FRONT BUMPER AIR GUIDE - RH <i>X su</i>	\$	59.00
5	FRONT BUMPER GUIDE SECTION-RH <i>X su</i>	\$	36.00
6	FRONT FENDER -RH <i>bt</i>	\$	722.00 <i>X</i>
7	FRONT FENDER ATTACHMENT PARTS <i>? X su</i>	\$	190.00
8	FRONT FENDER CLOSING ELEMENT -RH <i>? X su</i>	\$	47.00
9	FRONT FENDER BRACKET -RH <i>? X su</i>	\$	33.00
10	FRONT FENDER DEFORMATION ELEMENT-RH <i>? X su</i>	\$	46.00
11	FRONT FENDER BRACE-RH <i>? su</i>	\$	112.00
12	FRONT WHEEL HOUSING LINER -RH <i>? de</i>	\$	228.00 <i>190.80</i>
13	FRONT WHEEL HOUSING LINER ATTACHMENT PART-RH <i>? X su</i>	\$	86.00
14	FRONT WHEEL SPOILER <i>X su</i>	\$	69.00
15	FRONT SPOILER-RH <i>X su</i>	\$	34.00
16	FRONT STONE CHIP GUARD-RH <i>X su</i>	\$	48.00
17	FRONT STONE CHIP GUARD COVER-RH <i>X su</i>	\$	29.00
18	FRONT FENDER LEDGE TOP COVER-RH <i>X su</i>	\$	21.00
19	LED HEADLIGHT-RH <i>X su</i>	\$	7,321.00
20	FRONT ALUMINIUM RIM - RH <i>SCP</i>	\$	652.00 <i>547.20</i>
SUB-TOTAL SPARE PARTS CHARGES		: \$	12,104.00

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved