



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

CHINA TAIPING INSURANCE (S) PTE LTD

NO. 3
ANSON RD
SPRINGLEAF TOWER
SINGAPORE 079909

Contact :-

Fax No. : 62247175

Estimate : QUOT202006-000030(00)

Date : 01/06/2020

Vehicle No. : SLP7284A

Make/Model : MAZDA MAZDA3 SEDAN 1.5 AT
EU6

Mileage (km) : 0

Chassis No. : JM6BN22A8H0159661

Accident Date : 30/05/2020 00:00:00

Claim No. : SLH6250X

Reference : JO202006-0038

Policy No. : 5101262369-01

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Front bumper	1.0	867.00	867.00 ✓
2	Front bumper retainer	2.0	28.00	56.00 ✓
3	Front bumper clip	10.0	5.00	50.00 ✓
4	Front bumper cap RH	1.0	39.00	39.00 ✓
5	RH headlamp	1.0	1,071.00	1,071.00 ✓
6	Front grille	1.0	156.00	156.00 ✓
7	Front grille chrome RH	1.0	192.00	192.00 ✓
8	Front grille chrome base RH	1.0	28.00	28.00 ✓
9	Front RH fender	1.0	351.00	351.00 ✓
10	Front RH fender innershield	1.0	102.00	102.00 X
11	Front RH fender innershield clip	10.0	5.00	50.00 X
12	Washer tank	1.0	120.00	120.00 ✓
13	Front RH signal lamp	1.0	147.00	147.00 ✓
14	Front RH signal lamp cover	1.0	27.00	27.00 ✓
15	Front RH signal lamp finisher	1.0	21.00	21.00 X
16	Washer motor	1.0	72.00	72.00 X
17	RH taillamp	1.0	535.00	535.00 X
18	Rear bumper RH reflector	1.0	53.00	53.00 X
List Total :				3,937.00
20% Discount S\$				787.40
				3,149.60

LABOUR :

- To check wiring and lighting
- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts
- Spray painting on affected & replace parts

1.0 60.00 60.00
1.0 600.00 600.00
1.0 1,200.00 1,200.00

1,860.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CONTINUE NEXT PAGE

Page 1 of 2

Acknowledged by Repairer

Signature:

Date: