

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : LEONG DANIEL
19 NORMA TERRANCE
SINGAPORE 456560

Estimate No: EST1506000
Date: 30 May 2020
Policy No: P10096601R01
Veh Reg No: SGZ1285T
Make/Model: NISSAN NOTE 1.2 DIG-S
CVT 2WD LED
Chassis No: JN1TBAE12Z0982508
Engine No: HR12185885B
Reg. Date: 30/09/2016

ATTN:

Your Ref No: TP 0520-5982
Claim Type: Third Party
Accident Date: 29/05/2020
TP Veh Reg No: SHB 4466 H

Estimate Repair Cost to Vehicle No :SGZ1285T

Description	U/Price	Quantity	Price S\$	Amount S\$
Special Net				
1 REAR FENDER SIDE STICKER - RH	60.00	1 PC	60.00	60.00
Labour				
2 TO KNOCK OUT DENTS, RH REAR FENDER, RH REAR DOOR, REPAIR REAR BUMPER, REMOVE, REPLACE ACCIDENT PARTS	350.00	1 JOB	350.00	200
3 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.00	1 JOB	800.00	600
4 TO CHECK WIRING	20.00	1 JOB	20.00	X NN
			1,170.00	1,170.00

Total S\$ 1,230.00

Add GST @ 7% 86.10

Total Amount Payable S\$ 1,316.10

TOTAL: SINGAPORE DOLLAR ONE THOUSAND THREE HUNDRED SIXTEEN AND CENTS TEN ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3 Days.
part by part.
After repair photos.
11/6/2020.
Gmo Qiang - 8288022