

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Accident Date : 24.05.2020

*Not Authorized
61 Surp &
Resurvey After Paint
3-4 days*

Policy No: _____ Third Party

Date: 02.06.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Vios" Reg. No. SJG6134C Claiming Against Your Insured Reg. No. SKM289K		
1pc	Rear Bumper	5.00	<i>R</i> 435.00 ✓
10pcs	Rear Bumper Clips		<i>m</i> 50.00 —
1pc	Rear Bumper Top Retainer		<i>m</i> 100.00 X
1pc	Rear Bumper Bracket RH		<i>R</i> 70.00 X
1pc	Rear Bumper Reflector RH		<i>Sen R</i> 125.50 ✓
1pc	Rear Bumper Corner Retainer RH		<i>O/S</i> 101.50 ✓
1pc	Taillamp RH		<i>cn</i> 310.00 ✓
1pc	Taillamp Gasket		<i>m</i> 25.00 —
1pc	Taillamp Panel RH		<i>R</i> 135.00 X
1pc	End Panel		<i>R</i> 627.60 X
1pc	Boot Emblem		<i>m</i> 50.80 —
1pc	Boot Badge VIOS		<i>m</i> 48.00 —
1pc	Boor Badge E		<i>m</i> 37.70 ✓
1pc	Rear Exhaust Finisher		<i>sn</i> 187.00 X
			2,303.10
	Less 25%		575.78
			1,727.33
	Rear Bumper Reverse Sensor		<i>sn</i> 200.00 SN
	To Conduct Electrical Check, Replace Reverse Sensors, Module etc		120.00 201
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel Joint Sealant		<i>nn</i> 50.00 X
	Labour Charge - Panel Beating, Repairing Of Boot, End Panel, Cnt, Weld Taillamp Panel and Parts Replacement		800.00 400
	To Respray Affected Areas		700.00 400
			3,677.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: