

C

Kenneth

## TOTAL

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Accident Date : 24.05.2020

*Not Authorised*  
*U/Sump & 165dp*  
*Respray After Paint*  
*3-4 days*

Policy No: \_\_\_\_\_ Third Party

Date: 02.06.2020

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

| 数量<br>Quantity | 货 名<br>DESCRIPTION                                                                                             | 单 价<br>Unit Price | 银 Amount 额<br>\$ cts. |
|----------------|----------------------------------------------------------------------------------------------------------------|-------------------|-----------------------|
|                | Estimate Cost Of Repair To "Toyota Vios" Reg. No. SJG6134C<br>Claiming Against Your Insured Reg. No. SKM289K   |                   |                       |
| 1pc            | Rear Bumper                                                                                                    | 5.00              | 435.00 ✓              |
| 10pcs          | Rear Bumper Clips                                                                                              |                   | 50.00 —               |
| 1pc            | Rear Bumper Top Retainer                                                                                       |                   | 100.00 X              |
| 1pc            | Rear Bumper Bracket RH                                                                                         |                   | 70.00 X               |
| 1pc            | Rear Bumper Reflector RH                                                                                       |                   | 125.50 ✓              |
| 1pc            | Rear Bumper Corner Retainer RH                                                                                 |                   | 101.50 ✓              |
| 1pc            | Taillamp RH                                                                                                    |                   | 310.00 ✓              |
| 1pc            | Taillamp Gasket                                                                                                |                   | 25.00 —               |
| 1pc            | Taillamp Panel RH                                                                                              |                   | 135.00 X              |
| 1pc            | End Panel                                                                                                      |                   | 627.60 X              |
| 1pc            | Boot Emblem                                                                                                    |                   | 50.80 —               |
| 1pc            | Boot Badge VIOS                                                                                                |                   | 48.00 —               |
| 1pc            | Boor Badge E                                                                                                   |                   | 37.70 ✓               |
| 1pc            | Rear Exhaust Finisher                                                                                          |                   | 187.00 X              |
|                |                                                                                                                |                   | 2,303.10              |
|                |                                                                                                                |                   | 575.78                |
|                |                                                                                                                |                   | 1,727.33              |
|                | Less 25%                                                                                                       |                   |                       |
|                | Rear Bumper Reverse Sensor                                                                                     |                   | 280.00 SN             |
|                | To Conduct Electrical Check, Replace Reverse Sensors, Module etc                                               |                   | 120.00 200JA          |
|                | To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray<br>/ Replaced / Repair Panel Joint Sealant   |                   | 50.00 X               |
|                | Labour Charge - Panel Beating, Repairing Of Boot, End Panel, Cnt,<br>Weld Taillamp Panel and Parts Replacement |                   | 800.00 600A           |
|                | To Respray Affected Areas                                                                                      |                   | 700.00 400A           |
|                |                                                                                                                |                   | 3,677.33              |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: