



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 26/5/2020
 Vehicle: SLJ1375S
 Make / Model: NISSAN QASHQAI
 Chassis No: SJNFEAJ11U1719247

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	BONNET X R	1	\$ 961.40	\$ 961.40
2	FRONT BUMPER / DEF	1	\$ 1,855.00	\$ 1,855.00
3	FRONT BUMPER SPONGE X NN	1	\$ 195.70	\$ 195.70
4	FRONT BUMPER REINFORCEMENT X NN	1	\$ 665.40	\$ 665.40
5	FRONT BUMPER SIDE RETAINER RH / BR	1	\$ 35.20	\$ 35.20
6	FRONT BUMPER FOG LAMP OUTER CHROME RH / CRU	1	\$ 130.20	\$ 130.20
7	FRONT HEADLAMP RH / CRU	1	\$ 559.00	\$ 559.00
8	FRONT HEADLAMP LOWER BRACKET RH / CRU	1	\$ 38.10	\$ 38.10
9	FRONT HEADLAMP CLIPS RH X NN	1	\$ 28.10	\$ 28.10
10	FRONT GRILLE / BR	1	\$ 498.30	\$ 498.30
11	FRONT BUMPER FOG LAMP RH / BR	1	\$ 323.70	\$ 323.70
12	FRONT FENDER RH / DD	1	\$ 685.00	\$ 685.00
13	FRONT FENDER INNER COWLING RH / TM	1	\$ 121.30	\$ 121.30
14	FRONT SUPPORT PANEL X NN	1	\$ 617.50	\$ 617.50
15	WIPER WASHES TANK / CRU	1	\$ 162.50	\$ 162.50
16	WIPER WASHES TANK MOTOR X NN	1	\$ 95.60	\$ 95.60
17	RH FRONT DOOR X R	1	\$ 1,104.80	\$ 1,104.80
18	RH FRONT DOOR HING TOP X NN	1	\$ 87.90	\$ 87.90
19	RH FRONT DOOR HING BOTTOM X NN	1	\$ 87.90	\$ 87.90
20	RH FRONT DOOR CHECKER X NN	1	\$ 45.10	\$ 45.10
21	RH FRONT DOOR WEATHER STRIPE X NN	1	\$ 132.20	\$ 132.20
22	RH FRONT DOOR OUTER CHROME MOUDLING X NN	1	\$ 188.90	\$ 188.90
23	RH FRONT FENDER OUTER GARNISH X NN	1	\$ 654.00	\$ 654.00
24	RH FRONT SHOCK ABSORBER X NN	1	\$ 547.60	\$ 547.60
25	RH FRONT KNUCKLER ARM / BT	1	\$ 534.40	\$ 534.40
26	RH FRONT TIE ROD X NN	1	\$ 134.50	\$ 134.50
27	RH FRONT TIE ROD END X NN	1	\$ 121.00	\$ 121.00
28	RH FRONT STABILISED BAR X NN	1	\$ 353.60	\$ 353.60
29	RH FRONT STABILISED BAR LINK X NN	1	\$ 39.10	\$ 39.10
30	RH FRONT DRIVE SHAFT X (Low dlm) / 15	1	\$ 1,630.80	\$ 1,630.80
31	RH FRONT SHOCK ABSORBER TOP MOUNTING X NN	1	\$ 99.10	\$ 99.10
32	RH FRONT DOOR PILLAR X R	1	\$ 1,530.30	\$ 1,530.30
				\$ 14,263.20
			Less 10%	\$ 1,426.32
			Total	\$ 12,836.88

X
689 ✓

240.50 ✓

4017.20
 -19%
 3615.48

SLJ1375S

S/Nett items:				
1	RH FRONT TYRE X NN	1	\$ 280.00	\$ 280.00
2	RH FRONT RIM / (M)	1	\$ 1,681.50	\$ 1,681.50
3	FRONT BUMPER CLIP / M	1 SET	\$ 80.00	\$ 80.00
4	RH FRONT KNUCKLER ARM BEARING A / PP	1	\$ 332.30	\$ 332.30
5	MISCELLANEOUS X NN	1	\$ 200.00	\$ 200.00
				\$ 2,573.80
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	REMOVE AND RENEW RH FRONT UNDERCARRIAGE	1	\$ 300.00	\$ 300.00
3	TOWING FEE	1	\$ 120.00	\$ 120.00
4	REPAIR AND STRAIGHTEN CHASSIS FRAME	1	\$ 250.00	\$ 250.00
5	REMOVE AND TRANSFER RH FRONT DOOR FITTING	1	\$ 150.00	\$ 150.00
6	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 200.00	\$ 200.00
7	CONDUCT WHEEL ALIGNMENT	1	\$ 150.00	\$ 150.00
8	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
10	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
11	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00
				\$ 3,600.00
			Parts Replacement Amount	\$ 15,410.68
			Total Amount for Labour	\$ 3,600.00
			Total Amount	\$ 19,010.68

x
800 /
30 /
1162.30
30
200
80
X
X
X
60
X
30
500
1700

Steve (LKK) WML AL
3/6/20, 10.30am
5 days
L/S
My AL sig

P-3615-48
AI-1162-30
L-1799
6477-78
L/S - 5182.92
= 5299

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: