



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934
HP: 98888885

Estimation

Date: 26/5/2020

Vehicle: SLJ1375S

Make / Model: NISSAN QASHQAI

Chassis No: SJNFEAJ11U1719247

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	BONNET X R	1	\$ 961.40	\$ 961.40 X
2	FRONT BUMPER /	1	\$ 1,855.00	\$ 1,855.00 689 ✓
3	FRONT BUMPER SPONGE X NN	1	\$ 195.70	\$ 195.70 X
4	FRONT BUMPER REINFORCEMENT X NN	1	\$ 665.40	\$ 665.40 X
5	FRONT BUMPER SIDE RETAINER RH / BR	1	\$ 35.20	\$ 35.20 /
6	FRONT BUMPER FOG LAMP OUTER CHROME RH / CRT	1	\$ 130.20	\$ 130.20 /
7	FRONT HEADLAMP RH / CRT	1	\$ 559.00	\$ 559.00 /
8	FRONT HEADLAMP LOWER BRACKET RH / CRU	1	\$ 38.10	\$ 38.10 /
9	FRONT HEADLAMP CLIPS RH / X NN	1	\$ 28.10	\$ 28.10 X
10	FRONT GRILLE / BR	1	\$ 498.30	\$ 498.30 /
11	FRONT BUMPER FOG LAMP RH / BR	1	\$ 323.70	\$ 323.70 /
12	FRONT FENDER RH / DD	1	\$ 685.00	\$ 685.00 /
13	FRONT FENDER INNER COWLING RH / TM	1	\$ 121.30	\$ 121.30 /
14	FRONT SUPPORT PANEL X NN	1	\$ 617.50	\$ 617.50 X
15	WIPER WASHES TANK / CRU	1	\$ 162.50	\$ 162.50 /
16	WIPER WASHES TANK MOTOR / X NN	1	\$ 95.60	\$ 95.60 X
17	RH FRONT DOOR X R	1	\$ 1,104.80	\$ 1,104.80 X
18	RH FRONT DOOR HING TOP X NN	1	\$ 87.90	\$ 87.90 X
19	RH FRONT DOOR HING BOTTOM X NN	1	\$ 87.90	\$ 87.90 X
20	RH FRONT DOOR CHECKER X NN	1	\$ 45.10	\$ 45.10 X
21	RH FRONT DOOR WEATHER STRIPE X NN	1	\$ 132.20	\$ 132.20 X
22	RH FRONT DOOR OUTER CHROME MOUDLING X NN	1	\$ 188.90	\$ 188.90 X
23	RH FRONT FENDER OUTER GARNISH X NN	1	\$ 654.00	\$ 654.00 X
24	RH FRONT SHOCK ABSORBER / X NN	1	\$ 547.60	\$ 547.60 X
25	RH FRONT KNUCKLER ARM / BT	1	\$ 534.40	\$ 534.40 /
26	RH FRONT TIE ROD X NN	1	\$ 134.50	\$ 134.50 X
27	RH FRONT TIE ROD END X NN	1	\$ 121.00	\$ 121.00 X
28	RH FRONT STABILISED BAR X NN	1	\$ 353.60	\$ 353.60 X
29	RH FRONT STABILISED BAR LINK X NN	1	\$ 39.10	\$ 39.10 X
30	RH FRONT DRIVE SHAFT X (Low dlm) / 1/5	1	\$ 1,630.80	\$ 1,630.80 249.50 ✓
31	RH FRONT SHOCK ABSORBER TOP MOUNTING X NN	1	\$ 99.10	\$ 99.10 X
32	RH FRONT DOOR PILLAR X R	1	\$ 1,530.30	\$ 1,530.30 X
				\$ 14,263.20
			Less 10%	\$ 1,426.32
			Total	\$ 12,836.88

SLJ1375S

S/Nett items:				
1	RH FRONT TYRE X NN	1	\$ 280.00	\$ 280.00
2	RH FRONT RIM / (M)	1	\$ 1,681.50	\$ 1,681.50
3	FRONT BUMPER CLIP / M	1 SET	\$ 80.00	\$ 80.00
4	RH FRONT KNUCKLER ARM BEARING / M	1	\$ 332.30	\$ 332.30
5	MISCELLANEOUS X NN	1	\$ 200.00	\$ 200.00
				\$ 2,573.80
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	REMOVE AND RENEW RH FRONT UNDERCARRIAGE	1	\$ 300.00	\$ 300.00
3	TOWING FEE	1	\$ 120.00	\$ 120.00
4	REPAIR AND STRAIGHTEN CHASSIS FRAME	1	\$ 250.00	\$ 250.00
5	REMOVE AND TRANSFER RH FRONT DOOR FITTING	1	\$ 150.00	\$ 150.00
6	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 200.00	\$ 200.00
7	CONDUCT WHEEL ALIGNMENT	1	\$ 150.00	\$ 150.00
8	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
10	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
11	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00
				\$ 3,600.00
			Parts Replacement Amount	\$ 15,410.68
			Total Amount for Labour	\$ 3,600.00
			Total Amount	\$ 19,010.68

700 ✓
 30 ✓
 30 ✓
 80 ✓
 X ✓
 X ✓
 X ✓
 60 ✓
 X ✓
 30 ✓
 500 ✓

Steve (LKK) WML AL
 3/6/20, 10.30am
 5 days
 L/S
 My AL sig

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: