



MY CAR CREDIT PTE LTD

Reg no.: 202013105E

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934
HP: 98888885

Steve (LKK)

Estimation

Date: 2/6/2020

Vehicle: 2 dgs SDW6990J

Make / Model: BMW X3

Chassis No: WBAWX320700B26148

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / CK	1	\$ 1,530.00	\$ 1,530.00
2	REAR BUMPER REINFORCEMENT X NM	1	\$ 850.00	\$ 850.00
3	REAR BUMPER SIDE RETAINER LH	1	\$ 220.00	\$ 220.00
4	REAR BUMPER CENTER PAD (Black) / CK	1	\$ 160.00	\$ 160.00
5	REAR BUMPER REFLECTOR LH / CK	1	\$ 85.00	\$ 85.00
6	LH REAR TAILLAMP / BR	1	\$ 460.00	\$ 460.00
7	LH REAR TAILLAMP LOWER BARCKET ? / BR	1	\$ 112.00	\$ 112.00
8	REAR TAILGATE X NM	1	\$ 1,860.00	\$ 1,860.00
9	LH REAR TAILGATE LAMP / CK	1	\$ 350.00	\$ 350.00
10	LH REAR FENDER X NM	1	\$ 2,150.00	\$ 2,150.00
11	REAR END PANEL X NM	1	\$ 750.00	\$ 750.00
12	LH REAR TAILLAMP SIDE GARNISH X NM	1	\$ 95.00	\$ 95.00
13	REAR TAILGATE LOCK SENSOR X NM	1	\$ 125.00	\$ 125.00
			10%	\$ 8,747.00
			Less 5%	\$ 437.35
			Total	\$ 8,309.65
S/Nett items:				
1	SEALANT X NM	1	\$ 60.00	\$ 60.00
2	REAR BUMPER CLIP / CK	1 SET	\$ 80.00	\$ 80.00
3	MISCELLANEOUS X NM	1	\$ 200.00	\$ 200.00
				\$ 280.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	1	\$ 200.00	\$ 200.00
3	REMOVE AND REFIX REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00
4	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 150.00	\$ 150.00
5	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
6	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
7	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00
8	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
				\$ 2,730.00
			Parts Replacement Amount	\$ 8,589.65
			Total Amount for Labour	\$ 2,730.00
			Total Amount	\$ 11,319.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2625-30
M- 30
L- 610
3265-30

L/S- 2612-24
= 2600

2917
-19%
2625-30
30
30
30
30
250
300 610