

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: auburnauto.claim@gmail.com

Vehicle No: SKP40U

Model: BMW 523I

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
12	Front bumper side grille (RH) ^(centra) CR4	350.00 ✓
2	Front bonnet L/H & R/H fog lamp cover X \$ NN	440.00 X
1	Front bonnet lock Bump sensor (RH) - BR	380.00 295 ✓
1	Front bonnet inner rubber X NN	\$ 68.20 X
1	Front bonnet outer rubber X NN	\$ 86.20 X
1	Front bumper inner sponge ? X NN	\$ 135.90 X
1	Front bumper side retainers - BR	\$ 145.20 ✓
1	Front fender inner shield * fog lamp from RH \$ - BR	426.50 285 ✓
1	Front headlamp lower bracket ? X NN	\$ 286.00 X
1	Front grille chrome moulding X NN	\$ 285.90 X
1	Front grille logo - NN	\$ 288.00 90 ✓
1	Front grille (RH & LH) - BR (1pc - \$130) \$	825.00 260 ✓
1	Front Bumper - BR	\$ 1,850.00 1290 ✓
1	Front bonnet lock * Grille inner garnish ✓ BR	380.00 352 ✓
2	L/H and R/H Mud Flap X NN	\$ 160.00 X
1	L/H Headlight - BR	\$ 2480.00 ✓
1	R/H HeadLight - BR	\$ 2480.00 ✓
1	Car Plate and Carplate Holder - BR	\$ 190.00 60 ✓
1	Chrome "BMW" logo X NN	\$ 135.00 X

8087.20
- 19%
7278.48

~~\$ 9,431.90~~

c/f: \$

~~\$ 9,431.90~~

Special Nett Items

- 1 Rear Windscreen Sealant *N/N*
1 Front bumper clip */ AC*

AMT S\$

\$ 120.00 *X*

\$ 150.00 *30*

\$ 270.00

30

S/N.	Labour Charges		
	Remove and refit Front Bumper	\$	450.00 300
	Remove, refit and replaced damage lamps and check up rear electrical wiring	\$	150.00 30
	Remove and refit inner garnishes trim to assist repair	\$	200.00 X
	To apply undercoating on replaced panel	\$	120.00 30
	To Respray Painting.	\$	1,200.00 250
	Panel Beating	\$	1,200.00 X
		\$	<u>3,320.00</u>

GRAND TOTAL

\$ 13,021.90

P- 7278-48
 N- 30
 L- 610
 7918-48

L/S- 6334.78
 = 6350

610

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) Steve (LKK)
 (Contact) 8372 8913
 (Email) _____
 (Signature) 
 (Date/Time) 3/6/20, 2.00pm

WZ M
 L/S
 M AL sy
 3 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: