

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: auburnauto.claim@gmail.com

Vehicle No: SKP40U

Model: BMW 523I

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Front bumper side grille (RH) ?	\$ 350.00 135
2	Front bonnet L/H & R/H fog lamp cover X	\$ 440.00
1	Front bonnet lock Dump sensor (RH) - DR	380.00 195 ✓
1	Front bonnet inner rubber X	\$ 68.20
1	Front bonnet outer rubber X	\$ 86.20
1	Front bumper inner sponge ?	\$ 135.90
1	Front bumper side retainers - DR	\$ 145.20 ✓
1	Front fender inner shield X	\$ 426.50
1	Front headlamp lower bracket ?	\$ 286.00
1	Front grille chrome moulding X	\$ 285.90
1	Front grille logo - n/c	\$ 288.00 90 ✓
1	Front grille (RH & LH) - DR C1pc - \$130	\$ 825.00 260 ✓
1	Front Bumper - DR	\$ 1,850.00 1299 ✓
1	Front bonnet lock X	\$ 380.00
2	L/H and R/H Mud Flap X	\$ 160.00
1	L/H Headlight	\$ 2480.00
1	R/H HeadLight - DR	\$ 2480.00 ✓
1	Car Plate and Carplate Holder - DR	\$ 190.00 60 ✓
1	Chrome "BMWi" logo X	\$ 135.00

~~\$ 9,431.90~~

c/f: \$

~~\$ 9,431.90~~

Special Nett Items
1 Rear Windscreen Sealant
1 Front bumper clip / MC

AMT SS	
\$	120.00 X
\$	150.00 30
\$	270.00

S/N. **Labour Charges**

Remove and refit Front Bumper	\$	450.00	J00
Remove, refit and replaced damage lamps and check up rear electrical wiring	\$	150.00	J0
Remove and refit inner garnishes trim to assist repair	\$	200.00	X
To apply undercoating on replaced panel	\$	120.00	J0
To Respray Painting.	\$	1,200.00	250
Panel Beating	\$	1,200.00	X
	\$	<u>3,320.00</u>	

GRAND TOTAL

\$ 13,021.90

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) Steve (LKK)
(Contact) 8372 8813
(Email) _____
(Signature) 
(Date/Time) 3/6/20, 2.00pm

WHL AM
L/S
My PL ay
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: