



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKN361D

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 42632
Reg No/Reg Date SKN361D / 06/05/2014
Date In/Mileage 04/06/2020/ 92195
Chassis No WDD2221572A057881
Engine No 27696030642534
Make/Model MB/S 400 L Hybrid SEDAN (V22
Colour/Trim 021 183 Magnetite B/ 042 205 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WC000668	Credit	16/06/2020/ 09:13	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : 2100371969-05 // 3-4-2020
DRIVE IN/TP VEH NUMBER : 3-4-2020 // GBD3539Z - CHINA TAIPING
DATE IN/DATE SURVEY: 4-6-2020 1400 // Rasul - LKK
DIRECT SETTLEMENT BY : 6-4-2020 1130 // Cecilia - CHINA TAIPING

X PLUG	4.00	3.52	00.00	14.08
X COVER STRIP	1.00	63.61	00.00	63.61
A BPILAB				3360.00
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.				2400.00
A BPIRES				480.00
RESpray RH/FRONT FENDER & RH/FRONT DOOR & RH/REAR DOOR & RH/A-PILLAR RH/SIDE MIRROR COVER				600.00
A BPILAB				540.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				60.00
A BPILAB				1282.41
REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT				42.85
A BPILAB				3085.80
TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				305.97
S BPNSUB				7.07
LABOUR TO REMOVE AND INSTALL 1PC TYRE FROM RIM,(RUN FLAT)				17.69
WHEEL BALANCE AND INSTALL NEW VALVE HEAD	1.00	1282.41	00.00	309.21
X RIGHT FRONT FENDER	1.00	42.85	00.00	184.25
X RIGHT FRONT COVER, FENDER GAP	1.00	3085.80	00.00	
X RH/FRONT DOOR	1.00	305.97	00.00	
X RH/FRONT DOOR WEATHERSTRIP	1.00	7.07	00.00	
X RH/FRONT DOOR TOP SELF-ADHESIVE TRIM	1.00	17.69	00.00	
X RH/FRONT DOOR BOTTOM SELF-ADHESIVE TRIM	1.00	309.21	00.00	
X RIGHT FRONT DOOR, TOP TRIM STRIP	1.00	184.25	00.00	
X ADD. TURN SIGNAL LAMP				

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SKN361D

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 42632
Reg No/Reg Date SKN361D / 06/05/2014
Date In/Mileage 04/06/2020/ 92195
Chassis No WDD2221572A057881
Engine No 27696030642534
Make/Model MB/S 400 L Hybrid SEDAN (V22
Colour/Trim 021 183 Magnetite B/ 042 205 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WC000668	Credit	16/06/2020/ 09:13	CH	371 / Go Chee Han				
Description of Goods / Services								
X	RIGHT FRONT DISK WHEEL				1.00	799.19	00.00	799.19
X	RH/FRONT FENDER CHROME MOULDING				1.00	72.85	00.00	72.85
X	RH/FRONT DOOR CHROME MOULDING				1.00	159.27	00.00	159.27
X	RH/REAR DOOR CHROME MOULDING				1.00	159.27	00.00	159.27
X	PLUG				1.00	25.79	00.00	25.79
X	RIGHT MIRROR FRAME				1.00	1053.09	00.00	1053.09
X	RH INSIDE ANGLE BRACKET				1.00	7.98	00.00	7.98

Confirmed & accepted by

7% GST on **Nett** 15,030.38
15030.38 1052.13
Total Payable 16,082.51

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKN361D

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 42632
Reg No/Reg Date SKN361D / 06/05/2014
Date In/Mileage 04/06/2020/ 92195
Chassis No WDD2221572A057881
Engine No 27696030642534
Make/Model MB/S 400 L Hybrid SEDAN (V22
Colour/Trim 021 183 Magnetite B/ 042 205 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	16/06/2020/ 09:13	CH	371 / Go Chee Han
Description of Goods / Services				
				Amount

M BPNSUN

POLICY NO/ACC DATE : 2100371969-05 // 3-4-2020
DRIVE IN/TP VEH NUMBER : 3-4-2020 // GBD3539Z - CHINA TAIPING
DATE IN/DATE SURVEY: 4-6-2020 1400 // Rasul - LKK
DIRECT SETTLEMENT BY : 6-4-2020 1130 // Cecilia - CHINA TAIPING

				Amount
	4.00	3.52	00.00	14.08
X PLUG	1.00	63.61	00.00	63.61
X COVER STRIP	1.00	25.79	00.00	25.79
X PLUG	1.00	7.98	00.00	7.98
X RH INSIDE ANGLE BRACKET				

Confirmed & accepted by

7% GST on **Nett** 111.46
111.46 7.80
Total Payable 119.26

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany