



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKN361D

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 42632  
Reg No/Reg Date SKN361D / 06/05/2014  
Date In/Mileage / 0  
Chassis No WDD2221572A057881  
Engine No 27696030642534  
Make/Model MB/S 400 L Hybrid SEDAN (V22  
Colour/Trim 021 183 Magnetite B/ 042 205 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	04/04/2020/ 14:43	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : 2100371969-05 // 3-4-2020								
DRIVE IN/TP VEH NUMBER : 3-4-2020 // GBD3539Z - CHINA TAIPING								
DATE IN/DATE SURVEY:								
DIRECT SETTLEMENT BY :								
A BPILAB								
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW								
BODY PANELS AND REFINISH. (3-5 X966)								3360 3840.00
A BPIRES								
RESPRAY RH/FRONT FENDER & RH/FRONT DOOR & RH/REAR DOOR & RH/A-PILLAR								
RH/SIDE MIRROR COVER (4 panel)								
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
IDENTIFICATION STANDARD. NETT								0.02 2400 2800.00
A BPILAB								
REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.NETT								480.00
A BPILAB								
TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								600.00
S BPNSUB								
LABOUR TO REMOVE AND INSTALL TYRE FROM RIM,(RUN FLAT)								
WHEEL BALANCE AND INSTALL NEW VALVE HEAD					1.00	1282.41	00.00	1282.41
M RIGHT FRONT FENDER <i>bt</i>					1.00	24.53	00.00	24.53
M RIGHT FRONT FENDER ABSORBER <i>7.xm</i>					1.00	42.85	00.00	42.85
M RIGHT FRONT COVER, FENDER GAP <i>7.de</i>					1.00	227.44	00.00	227.44
M RH/F WHEEL HOUSE COVERING <i>7.xsvl</i>					1.00	3085.80	00.00	3085.80
M RH/FRONT DOOR <i>bt</i>					1.00	305.97	00.00	305.97
M RH/FRONT DOOR WEATHERSTRIP <i>new</i>					1.00	7.07	00.00	7.07
M RH/FRONT DOOR TOP SELF-ADHESIVE TRIM <i>new</i>					1.00	17.69	00.00	17.69
M RH/FRONT DOOR BOTTOM SELF-ADHESIVE TRIM <i>new</i>					1.00	309.21	00.00	309.21
M RIGHT FRONT DOOR, TOP TRIM STRIP <i>bt de</i>					1.00	184.25	00.00	184.25
M RH/ADD. TURN SIGNAL LAMP <i>cm</i>					1.00			

Confirmed & accepted by

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKN361D

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
6222366

### Vehicle & Document Information

WIP No 42632  
Reg No/Reg Date SKN361D / 06/05/2014  
Date In/Mileage / 0  
Chassis No WDD2221572A057881  
Engine No 27696030642534  
Make/Model MB/S 400 L Hybrid SEDAN (V22  
Colour/Trim 021 183 Magnetite B/ 042 205 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	04/04/2020/ 14:43	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RIGHT MIRROR BOWL <i>repair</i>	1.00	184.27	00.00	184.27 <i>12</i>
M RIGHT MIRROR FRAME <i>repair</i>	1.00	970.60	00.00	970.60 <i>1053.49</i>
M RIGHT FRONT DISK WHEEL <i>scr</i>	1.00	799.19	00.00	799.19
M RH/FRONT FENDER CHROME MOULDING <i>acc</i>	1.00	72.85	00.00	72.85
M RH/FRONT DOOR CHROME MOULDING <i>acc</i>	1.00	159.27	00.00	159.27
M RH/REAR DOOR CHROME MOULDING <i>acc</i>	1.00	159.27	00.00	159.27

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

*Paul*  
*Hp 90010068*

*7 days*

*04/06/2020 @ 1400hrs*

*Reg before paint*

Confirmed & accepted by

7% GST on **Nett** 16,152.67  
16152.67 1130.69

**Total Payable** 17,283.36

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg