

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20006109/R1SF3E2

**Date:** 19/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800083927
<b>Claimant Vehicle No :</b> FBP6095D	<b>Insured Vehicle No :</b>	SMC6653G
Date of Loss: 04/04/2020	Nature of Claim: TP	Claim No: 2736203561SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP6095D	Engine No:	G3E6E0484943
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740K0152783
Reg. Date:	07/05/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Multi-colour		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	120/70-17
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	03/06/2020	Inspected At:	M1 Motoring
Date Inspected:	03/06/2020		34 Toh Guan Road East, #01-29
			Singapore 608579
Estimated Period of Repair:	4.0 days		

**Adjuster:** MOHD RASUL

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT RIM	Scratched	0.00 F	*- F
3	1		*FRONT FENDER WHEEL GUARD	Missing	0.00 F	*- F
4	1		*FRONT BRAKE DISC	Scratched	0.00 F	*- F
5	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
6	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
7	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
8	1		*FRONT HEADLAMP	Cracked	0.00 F	*- F
9	1		*FRONT HEADLAMP FAIRING	Scratched	0.00 F	*- F
10	1		*FRONT LH SIGNAL LAMP	Broken	0.00 F	*- F
11	1		*FRONT RH SIGNAL LAMP	Broken	0.00 F	*- F
12	1		*BRAKE RESERVOIR	Scratched	0.00 F	*- F
13	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
14	1		*SIDE FAIRING REAR	Scratched	0.00 F	*- F
15	1		*FRONT FAIRING	Scratched	0.00 F	*- F
16	1		*FRONT FAIRING GARNISH	Scratched	0.00 F	*- F
17	1		*BASKET	Bent	0.00 F	*- F
18	1		*RADIATOR	Bent	0.00 F	*- F
19	1		*FOOT BRAKE	Bent	0.00 F	*- F
20	1		*FRONT FOOT REST	Broken	0.00 F	*- F
21	1		*REAR FOOTREST	Scratched	0.00 F	*- F
22	1		*REAR FOOT REST BRACKET	Scratched	0.00 F	*- F
23	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
24	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F
25	1		*HANDLE BAR GRIP RH	Cut	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**