55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 35916

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1

Contact No : 6366 2323 Fax No : 6841 1183

Reference : PA/OD/0398/2020/NS

Date : 28-May-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ee Tiang Lee Cyril

Address : 39 Jalan Keruing

Singapore 808959

Telephone : HP +65 97729940

Type of Claim : Own Damage Claims

Policy No. : 1800126389-01

Vehicle No : EE 2080 U

Model Code : Audi A3 Sedan 1.4 TFSI

Model / Year : Oct-18
Engine No : CZE 802037

Chassis No : WAUZZZ8V0J1082385

Mileage : Date In : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 21-May-20

Place of Accident : Ang Mo Kio Blk 628 Carpark A70

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EE 2080 U

C ()		Damage Parts & Prices		
S/N	Parts Description	 S/Nett Remarks		
1	FRONT BUMPER Defund	\$ 1,894.00 ✓		
2	FRONT BUMPER FIXING PARTS Not have	\$ 176.00 >		
3	FRONT BUMPER GUIDE SECTION - RH Not 1	\$ 36.00 >		
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE KLC	\$ 505.00 🙏		
5	FRONT BUMPER CLOSING ELEMENT - RH 2	\$ 280.00 +		
6	FRONT BUMPER COVER TRIM - RH	\$ 153.00 +		
7	WHEEL HOUSING LINER ADAPTER - RH	\$ 36.00 €		
8	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 177.00 +		
9	FRONT FENDER - RH Deutla	\$ 802.00		
10	FRONT FENDER ATTACHMENT PARTS Nen	\$ 68.00		
11	FRONT FENDER BRACKET - RH	\$ 36.00		
12	FRONT FENDER BRACE	\$ 90.00 7		
13	WHEEL HOUSING LINER - RH ise an	\$ 159.00 🖈		
14	WHEEL HOUSING LINER ATTACHMENT PARTS NEW	\$ 84.00 4		
15	LED HEADLIGHT - RH Z	\$ 5,193.00 *		
16	LIFT CYLINDER - RH	\$ 134.00 +		
17	FRONT ALUMINIUM RIM - RH LLT	\$ 666.00		
18	SUNDRIES	\$ 300.00 ?		
	TOTAL SPARE PARTS CHARGES : TOTAL LABOUR CHARGES : GRAND TOTAL :	\$ 10,789.00 5,282.00 16,071.00		

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699

Telefax

Estimated Labour Charges for Accident Vehicle EE 2080 U

S/N Nature of Jobs				Stimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	/
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$	2,450.00	1000
3	To respray front bumper and rhs front fender.		\$	2,000.00	1100
4	To renew rhs front rim and carry out wheel alignment.	S/N	\$	280.00	
5	To carry out diagnostic check.	S/N	\$	192.00	
	TOTAL LABOUR CHARGES	: :	\$5	,282.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
 Parts prices are subject to confirmation

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Not authorsed, or Days

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant