

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT120006114/44f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

27A 14621 51 4yrs. bnd...
Dep 5800 net 10379

7/7/20 confirmed 4/5 & 4800 w.h. Ray

Veh No:

5J4831KM

Yr Regn:

12 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota Vios

Colour

Blue

Sp. Reading

168018

Eng/No:

C/No:

MR253HY9325131741

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size:

F:

18.

R:

195/55-R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

R/Bal.

L/Bal.

D.O.A.

2/6/20

Rear

R/Bal.

L/Bal.

D.O.I.

6

mm

6

mm

3/6/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, S SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

Not Affected
2/5 = 4800/
Take the Affected
8 days.

M/S: NURASHAKIRIN HISAM
BLK 423 CHOA CHU KANG AVE 4 #05-252
SINGAPORE 680423

Estimate No: EST1506003
Date: 02 Jun 2020
Policy No: MT/00746681
Veh Reg No: SJU8314M
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305131741
Engine No: 1NZX976358
Reg. Date: 30/12/2009

ATTN: CHINA TAIPING
Your Ref No: TP 0620-5984
Claim Type: Third Party
Accident Date: 02/06/2020
TP Veh Reg No: GBG 7987 X

Estimate Repair Cost to Vehicle No :SJU8314M

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT <i>Body</i>	549.7000	1 PCS	549.70	✓
2 REAR BOOT TOYOTA LOGO <i>neu</i>	68.4000	1 PC	68.40	✓
3 REAR BOOT 1.5 WORDING <i>neu</i>	50.6000	1 PCS	50.60	✓
4 REAR BOOT E WORDING <i>neu</i>	51.7000	1 PCS	51.70	✓
5 REAR BOOT TOP LOCK <i>neu</i>	68.7000	1 PCS	68.70	✓
6 REAR BOOT BOTTOM LOCK <i>neu</i>	54.7000	1 PC	54.70	X
7 REAR BOOT NUMBER PLATE LAMP - LH/RH <i>neu</i>	62.5000	2 PCS	125.00	X
8 REAR BOOT RUBBER <i>neu</i>	148.7000	1 PC	148.70	✓
9 REAR BOOT OUTER GARNISH <i>neu</i>	210.5000	1 PCS	210.50	✓
10 REAR PANEL <i>Body</i>	380.4000	1 PCS	380.40	✓
11 REAR PANEL TOP GARNISH <i>neu</i>	158.6000	1 PCS	158.60	✓
12 REAR BUMPER <i>neu</i>	310.4000	1 PC	310.40	✓
13 REAR BUMPER CLIPS <i>neu</i>	5.5000	10 PC	55.00	✓
14 REAR BUMPER SIDE HOLDER - LH <i>neu</i>	85.4000	1 PCS	85.40	X
15 REAR BUMPER SIDE HOLDER - RH <i>neu</i>	85.4000	1 PCS	85.40	✓
16 REAR BUMPER CENTRE RETAINER - LH <i>neu</i>	68.7000	1 PCS	68.70	X
17 REAR BUMPER CENTRE RETAINER - RH <i>neu</i>	68.7000	1 PCS	68.70	✓
18 REAR BUMPER BRACKETS - LH <i>neu</i>	78.4000	1 PC	78.40	X
19 REAR BUMPER BRACKETS - RH <i>neu</i>	78.4000	1 PC	78.40	X
20 REAR BUMPER LAMP - LH <i>neu</i>	80.5000	1 PC	80.50	X
21 REAR BUMPER LAMP - RH <i>neu</i>	80.5000	1 PCS	80.50	✓
22 REAR TAILLAMP - LH <i>neu</i>	210.7000	1 PC	210.70	✓
23 REAR TAILLAMP - RH <i>neu</i>	210.7000	1 PC	210.70	✓
24 TAILLAMP PANEL - RH <i>neu</i>	129.4000	1 PCS	129.40	✓
25 REAR ENDER - RH <i>neu</i>	718.5000	1 PCS	718.50	X
26 REAR GLASS MOULDING <i>neu</i>	148.3000	1 SET	148.30	X
27 FRONT BUMPER <i>neu</i>	318.2000	1 PC	318.20	✓
28 FRONT BUMPER CLIPS <i>neu</i>	5.5000	10 PC	55.00	✓
29 FRONT BUMPER REINFORCEMENT <i>neu</i>	240.3000	1 PC	240.30	✓
30 FRONT BUMPER SIDE HOLDER - LH <i>neu</i>	80.4000	1 PC	80.40	X
31 FRONT BUMPER SIDE HOLDER - RH <i>neu</i>	80.4000	1 PC	80.40	X
32 FRONT BUMPER CENTRE GRILLE <i>neu</i>	79.7000	1 PCS	79.70	✓
33 GRILLE W/CHROME MOULDING ASSY <i>neu</i>	280.3000	1 PCS	280.30	X
34 FRONT BUMPER TOYOTA LOGO <i>neu</i>	98.7000	1 PCS	98.70	✓
35 FRONT BUMPER FOAM <i>neu</i>	105.3000	1 PC	105.30	X
36 FRONT HEADLAMP - RH <i>neu</i>	313.9000	1 PC	313.90	X

3630

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road I #01-45/46 Singapore 408718
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO: 01006949C

Our No Consultants hence notify the Repairer of the following:
 • Third party survey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

M/S: NURASHAKIRIN HISAM
 BLK 423 CHOA CHU KANG AVE 4 #05-252
 SINGAPORE 680423

Estimate No: **EST1506003**
 Date: 02 Jun 2020
 Signature: _____
 Date: _____
 Policy No: MT/00746681

ATTN: CHINA TAIPING
 Your Ref No: TP 0620-5984
 Claim Type: Third Party
 Accident Date: 02/06/2020
 TP Veh Reg No: GBG 7987 X

Veh Reg No: **SJU8314M**
 Make/Model: TOYOTA VIOS E AUTO
 Chassis No: MR053HY9305131741
 Engine No: 1NZX976358
 Reg. Date: 30/12/2009

Estimate Repair Cost to Vehicle No :SJU8314M

Description	U/Price	Quantity	Price S\$	Amount S\$
			5,928.20	
		Less 25%	1,482.05	4,446.15
Special Net				
37 REAR NUMBER PLATE WITH CASING	45.0000	1 SET	45.00	40
38 FRONT NUMBER PLATE WITH CASING	45.0000	1 SET	45.00	40
39 REAR BUMPER SENSOR	220.0000	1 SET	220.00	200
40 SPONGE TAPE	20.0000	1 PCS	20.00	X
41 SEALANT	20.0000	2 PC	40.00	X
			370.00	370.00
Labour				
42 TO KNOCK OUT DENTS, STRAIGHTEN CHASSIS, REAR TYRE FLOOR PANEL, CUT/WELD REAR PANEL, RHR FENDER, REMOVE, REPLACE ACCIDENT PARTS	1,800.000	1 JOB	1,800.00	1200
43 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,300.000	1 JOB	1,300.00	1200
44 TO CHECK WIRING	50.0000	1 JOB	50.00	30
45 TO REMOVE, REFIX REAR GARNISH	150.0000	1 JOB	150.00	60
46 TO TUFF-KOTE	120.0000	1 JOB	120.00	60
47 TO REMOVE, REPAIR REAR EXHAUST PIPE	100.0000	1 JOB	100.00	X
48 TO REMOVE, REFIX REAR GLASS	150.0000	1 JOB	150.00	X
			3,670.00	3,670.00
Total			S\$ 8,486.15	
Add GST @ 7%			594.03	
Total Amount Payable			S\$ 9,080.18	

TOTAL: SINGAPORE DOLLAR NINE THOUSAND EIGHTY AND CENTS EIGHTEEN ONLY

Supp 1.

For Progressive Car Care Pte Ltd

1 pc spare tyre board. 280.90 ✓
 1 pc RHR tool Foam RH 210.30 ✓
 1 pc RHR fender side lower shield 80.50 ✓
 2 pcs taillamp gasket L/R @ 50.20 x 2 = 100.40 ✓
 4 pcs taillamp clips @ 5.50 x 4 = 22.00 ✓

AUTHORISED SIGNATURE

1-4302-1
 252
 P-3226-57
 S.N. 280.00
 L-2530.00
 6086.57
 4885

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road
Springleaf Tower #16-00
Singapore 079909

TEL: 63896111 FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Your Ref No: TP 0620-5984

Claim Type: Third Party

Accident Date: 02/06/2020

TP Veh Reg No: GBG 7987 X

Estimate No: EST1506003

Date: 03 Jul 2020

Policy No: MT/00746681

Veh Reg No: SJU8314M

Make/Model: TOYOTA VIOS E AUTO

Chassis No: MR053HY9305131741

Engine No: 1NZX976358

Reg. Date: 30/12/2009

Estimate Repair Cost to Vehicle No :SJU8314M

Description	U/Price	Quantity	Price S\$	Amount S\$
Supplementary Parts to Repair				
List Price				
1 SPARE TYRE BOARD <i>Torn</i>	280.9000	1 PC	280.90	✓
2 REAR TOOL FOAM - RH <i>Torn</i>	210.3000	1 PC	210.30	✓
3 REAR FENDER SIDE SHIELD - RH <i>Torn</i>	80.5000	1 PC	80.50	✓
4 REAR TAILLAMP GASKET - LH/RH <i>all</i>	50.2000	2 PCS	100.40	✓
5 REAR TAILLAMP CLIP <i>all</i>	5.5000	4 PCS	22.00	✓
			694.10	X
	Less 25%		173.53	520.58
			Total	S\$ 520.58
			GST Amount	S\$ 36.44
			Total Amount Payable	S\$ 557.02

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

[Handwritten Signature]
SUPP 50.00
PARTS 272.50
SN 280.00
LAB 250.00
6073.08
1/3 = 4850.