

SHENG LI LAI

2 Kaki Bukit Ave 2 (Kaki Bukit Auto Hub), #01-36, Singapore 417921

H/P: 9111 9222 (Low Eng Chong) Tel: 6842 0302 Fax: 6746 0295

Email: slshenglilai@gmail.com

To Chiew
Dennis

Vehicle number: GBD4751U

Vehicle Made & Model: TOYOTA DYNA

Qty	List Items	Amount \$
1	Rear taillamp - RH } Smashed	291.33 ✓
1	Rear taillamp panel - RH	221.50 ✓
1	Rear tailgate lower member } Not new	481.90 ✓
1	Rear sidegate lower member - RH	481.90 ✓
1	Rear canopy front partition panel Repair	1,210.50 ✓
1	Rear canopy floor compartment panel Distorted	1,265.50 ✓
1	Rear exhaust pipe Not new	481.65 ✗
1	Front door rear pillar - RH Repair	511.30 ✓
1	Front door rear pillar emblem new	68.85 ✓
1	Front cabin rear rock carrier member - CTR Repair	861.90 ✓
2	Engine mountings - L/R @ 211.50 Not new	423.00 ✓
1	Gear box mounting Not new	189.60 ✓
1	Air cleaner resonator included	681.90 ✓
		<hr/>
		Sub-total 7,170.83
		Less 25% 1,792.71
		<hr/> Total List 5,378.12

2529.08
1896.81

Special Nett Items

1 set	Rear canopy box assy Distorted	7,500.00 5000
1 set	Rear canopy box wooden board new	1,200.00 400
1 set	Rear canopy lower bolt set new	180.00 80
1 set	Rear reverse sensor Damaged	280.00 200
		<hr/>
	Total Special Nett	9,160.00

5670

Vehicle number: GBD4751U

Vehicle Made & Model: TOYOTA DYNA

Labour charges

To check rear electrical wiring	120.00	30
To reinstall rear whole canopy to assist repair	800.00	500
To straighten, repair & realign rear chassis frame member	1,200.00	X
To remove, refix rear exhaust	80.00	X
To respray undercoating	150.00	80
To respray painting and etc	1,200.00	500
Panel beating, cut, weld remove & replacing above parts	1,200.00	500
Total Labour	4,750.00	

1610

total: 9186.81
4/s: 7.3K.
14 Days

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 19,288.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: