

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle, SMD 74781

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To remove and renew aircond condenser, radiator and charged air cooler. Check electrical fans and control unit. Pressurise cooling system. To arry out vacuum and reqas.	S/N \$ 1,200.00 X	
3	To dismantle and renew front bumper, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. S/S	\$ 4,900.00 <del>S/S</del> 1250	
4	To respray front bumper and bonnet. S/S	\$ 2,000.00 <del>S/S</del> 1100	
5	To carry out first measurement test on car o-liner. <i>Photo</i>	S/N \$ 800.00 ? X	
<b>SUB TOTAL LABOUR CHARGES</b>		<b>\$ 9,380.00</b>	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2223 Fax : 6841 1103

Telefax

## Estimated Labour Charges for Accident Vehicle, SMD 7478J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 /	
7	To renew both rear 1/4 glass and rear windscreen to facilitate fender renewal.	S/N \$ 900.00 /	
8	To remove and reinstall rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 /	
9	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. Inspect for damage and renew where necessary. <i>photo</i>	S/N \$ 1,400.00 ? /	
10	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc. <i>photo</i>	S/N \$ 1,400.00 ? /	
<b>SUB TOTAL LABOUR CHARGES</b>		<b>: \$ 4,340.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle, SMD 74781

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
(11)	To dismantle and reinstall centre console. Renew airbag control unit and both front seatbelt.	S/N \$ 1,800.00 X	
12	To remove and reinstall exhaust system and rear suspension assembly, including rear axle. Renew accordingly. <i>photo</i>	S/N \$ 2,400.00 ?	/
13	To remove and reinstall fuel tank assy. <i>photo</i>	S/N \$ 600.00 ?	/
14	To setup vehicle on car-o-liner for repair. <i>photo</i>	S/N \$ 2,400.00 ?	/
15	To dismantle and renew rear bumper and rear lid. Cut out and weld rear end panelling inner and outer, spare wheel housing and both rear fenders. Re-organise rear crash management components. Reinstall all parts removed. <i>500</i>	2 x S/N \$ 13,300.00 <i>19 days</i>	<i>2007 7000</i> <i>9500</i>
SUB TOTAL LABOUR CHARGES		: <u>\$ 20,500.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle, SMD 74781

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
16	To carry out stone chip primer work on rear panelling and spare wheel housing. <i>photo</i>	S/N \$ 780.00 ?	/
17	To respray rear bumper, rear lid, hinges, both rear fenders, (both sill panels, drain panels, roof channel, door entrances) End panelling, spare x 3 wheel housing and boot floor. To carry out stone chip treatment, cavity preservation and joint sealer works. <i>SSO</i>	\$ 10,600.00 <i>4050 4050 5150</i>	/
18	To carry out wheel alignment. <i>photo</i>	S/N \$ 240.00 ?	/
19	To install rear windscreen solar film. <i>photo</i>	S/N \$ 400.00 ?	/
20	To carry out diagnostic check.	S/N \$ 384.00 <i>192, 384</i>	/
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 46,624.00</b>	

*14312*

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 7478 J

S/N	Parts Description		Damaged Parts S/Nett	Prices & Remarks
1	FRONT BUMPER / CR4	\$	2,068.00	1654.40 /
2	FRONT BUMPER FIXING PARTS X NNI	\$	269.00	
3	FRONT BUMPER GRILLE - CENTRE / BR	\$	185.00	147.60 /
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X NNI	\$	198.00	
5	FRONT BUMPER AIR GUIDE - LH / RH ? X NNI	2 \$	118.00	
6	FRONT BUMPER SECURING STRIP / MC	2 \$	67.00	52.96 /
7	RADIATOR GRILLE / BR	\$	1,254.00	1003.20 /
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH X NNI	2 \$	254.00	
9	FRONT BUMPER CARRIER ? / BR	\$	757.00	605.20 /
10	FRONT BUMPER FOAM FILLER PIECE ? / BR	\$	117.00	93.60 /
11	FRONT BUMPER COVER / DR	\$	120.00	96.00 /
12	FRONT BUMPER GUIDE SECTION - LH ? / TM	\$	34.00	27.12 /
13	FRONT BUMPER GUIDE SECTION - RH ? / TM	\$	36.00	28.16 /
14	FRONT BUMPER BRACKET (LH/RH) ? / MC BT	2 \$	428.00	342.40 /
15	CAUTION SIGN STICKER / MC	NEC \$	13.00	10.24 /
16	AIRCON STICKER / MC	NEC \$	7.00	5.36 /
17	LOCK CARRIER BRACKET ? / BR	\$	129.00	103.20 /
18	FRONT BUMPER SUPPORT (LH/RH) ? / MC	2 \$	54.00	42.24 /
19	FRONT PARKING AID SENSOR - INNER / OUTER ? X NN	2	TBC	
20	FRONT PARKING AID SEAL RING / TR X NN	4 \$	14.00	
SUB TOTAL SPARE PARTS		:	<u>\$ 6,122.00</u>	

3728

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMD 74781

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S	5/Nett	
21	HORN - LH HIGH TONE X N/AI	S	38.00	
22	HORN - RH LOW TONE X N/AI	S	270.00	
23	SPRING SHACKLE - LH / RH X N/AI	2 S	54.00	
24	NOISE INSULATION Y N/AI	S	537.00	
25	BONNET X X R / 00	S	2,634.00	2107.20 /
26	BONNET ATTACHMENT PARTS X N/AI	S	116.00	
27	BONNET IMPACT PROTECTION - CENTRE Y N/C	S	26.00	20.56 /
28	BONNET IMPACT PROTECTION - LH Y N/C	S	26.00	20.80 /
29	BONNET IMPACT PROTECTION - RH X N/C	S	26.00	20.56 /
30	BONNET BOWDEN CABLE X N/AI	S	54.00	43.20 /
31	BONNET BOWDEN CABLE - CENTRE Y N/AI	S	54.00	
32	BONNET LID LOCK X N/AI	2 S	403.00	
33	BONNET RELEASE LEVER X N/AI	S	13.00	
34	BONNET STRIKER - LH / RH X N/C	2 S	94.00	75.04 /
35	LED HEADLIGHT - LH / RH X N/AI (LH) - BR 1.2	2 S	14,642.00	5856.80 /
36	LIFT CYLINDER - LH / RH X N/AI	2 S	396.00	
37	HEADLIGHT CORRUGATED PIPE ? X N/AI	S	88.00	
38	LOCK CARRIER X N/AI	S	956.00	
39	AIRCON CONDENSER X N/AI	S	586.00	
40	CHARGE AIR COOLER X N/AI	S	552.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>: \$ 21,565.00</b>		

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMD 74781

Damaged Parts & Prices  
S/Nett Remarks

S/N	Parts Description				
41	RADIATOR X NN	\$	766.00		
42	READY, IX COOLANT Y NN	\$	26.00		
43	RADIATOR AIR GUIDE LH/RH <del>1</del> - nec	2 \$	54.00	42.98 /	
44	RADIATOR AIR GUIDE LH/RH INNER <del>2</del> - nec	2 \$	24.00	17.76 /	
45	RADIATOR AIR GUIDE - UPPER Y NN	\$	15.00		
46	RADIATOR AIR GUIDE - LOWER X NN	\$	21.00		
47	REAR BUMPER / BR	\$	2,079.00	1663.29 /	
48	REAR BUMPER FIXING PARTS X <del>nec</del> X NN	\$	69.00		
49	REAR BUMPER SECURING STRIP / nec	\$	210.00	168 /	
50	REAR BUMPER SPOILER / CRH	\$	234.00	187.20 /	
51	REAR LIGHT REFLECTOR LH/RH (BR / LH side) NN X	12 \$	78.00	34 30.64 /	
52	REAR BUMPER CARRIER / DD	\$	845.00	675.60 /	
53	REAR BUMPER SEAL / nec	2 \$	26.00	20.80 /	
54	REAR BUMPER GUIDE SECTION - LH ? / BR	\$	41.00	32.80 /	
55	REAR BUMPER GUIDE SECTION - RH ? / BR	\$	43.00	37.68 /	
56	REAR BUMPER GUIDE SECTION - LH/RH ? / BR	2 \$	42.00	33.12 /	
57	REAR PARKING AID SENSOR - INNER / OUTER / SLA	4 \$	TBC	369.00 /	
58	REAR PARKING AID SEAL RING / nec	4 \$	14.00	10.56 /	
59	REAR BUMPER WIRING SET ? / TN	\$	633.00	506.00 /	
60	BOOT LID CONTROL UNIT ? X NN	\$	392.00		

SUB TOTAL SPARE PARTS

: \$ 5,672.00

3516

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMD 74781

Damaged Parts & Prices  
S/Nett Remarks

S/N	Parts Description				
61	TAILGATE OPENING SENSOR LINE ? / BR	\$	194.00	154.80 /	
62	REAR CROSS AERIAL ACCESS ? X NN	\$	105.00		
63	REAR LID / NN	\$	2,496.00	1996.80 /	
64	REAR LID HINGE - LH / RH / OT	2 \$	432.00	344.80 /	
65	REAR LID LOCK / OT	\$	217.00	173.20 /	
66	REAR LID ATTACHMENT PARTS / MC	\$	137.00	109.60 /	
67	LID LOCK PUSH BUTTON / (M) (CMTA)	\$	1,267.00	1013.60 /	
68	REAR LID LOCK STRIKER ? / OT	\$	31.00	24.40 /	
69	ANTI THEFT GUARD COVER - INNER ? / BR	\$	60.00	47.44 /	
70	REAR LID FLAP GASKET ? / CRY	\$	193.00	154.40 /	
71	PACKING ADHESIVE / MC	2 \$	18.00	14.24 /	
72	AUDI EMBLEM / MC	\$	117.00	93.20 /	
73	A4 INSCRIPTION / MC	2 \$	90.00	71.76 /	
74	TFSI INSCRIPTION / MC	\$	90.00	71.76 /	
75	REAR CROSS PANEL ?	\$	245.00	195.60 /	
76	REAR CROSS PANEL REINFORCEMENT ? / DD	2 \$	475.00	389.90 /	
77	SPARE WHEEL WELL ? / DD	4 \$	2,095.00	1676.00 /	
78	REAR LID TRIM PANEL ? / BR	4 \$	310.00	247.60 /	
79	REAR CROSS PANEL TRIM ? / BR	\$	156.00	124.50 /	
80	LUGGAGE COMPARTMENT FLOOR ? X NN	\$	254.00		

SUB TOTAL SPARE PARTS

: \$ 8,982.00

48844

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMD 74781

S/N	Parts Description			Damaged Parts & Prices S/Nett	Remarks
81	LUGGAGE COMPARTMENT FLOOR ? X N/A		\$	669.00	
82	STOWAGE COMPARTMENT ? X N/A		\$	49.00	
83	REAR SILENCER - LH ✓ BT		\$	831.00	664.80 /
84	REAR SILENCER DUAL CLIP ✓ MC		\$	46.00	36.48 /
85	REAR SILENCER - RH ? X N/A		\$	831.00	
86	REAR SILENCER DUAL CLIP ✓ MC		\$	46.00	36.48 /
87	EXHAUST SILENCER BRACKET ? X N/A	2	\$	79.00	
88	REAR SILENCER HEAT SHIELD - LH / RH (RH) ✓ BT	1.2	\$	286.00	<del>243</del> 114.00 /
89	HEAT SHIELD CENTRE ? X N/A		\$	64.00	
90	LED TAIL LIGHT - (LH) / (RH) ✓ BR	2	\$	1,918.00	1534.40 /
91	TAIL LIGHT TRIM - (LH) / (RH) ✓ CVT	2	\$	56.00	44.32 /
92	LED TAIL LIGHT - (LH) / (RH) ✓ BR	2	\$	1,918.00	1534.40 /
93	TAIL LIGHT TRIM - (LH) / (RH) ✓ CVT	2	\$	56.00	44.32 /
94	LED LICENSE PLATE LIGHT ? X N/A	2	\$	195.00	
95	SIDE PANEL - (LH) / (RH) ✓ DD	2	\$	5,036.00	4028.80 /
96	SIDE WINDOW - (LH) / (RH) ✓ MC	2	\$	1,158.00	926.40 /
97	SEATBELT - LH X N/A		\$	1,005.00	
98	SEATBELT - RH X N/A		\$	1,040.00	
99	SEAT BELT HEIGHT ADJUSTER X N/A	2	\$	329.00	
100	AIRBAG CONTROL UNIT X N/A		\$	1,986.00	
SUB TOTAL SPARE PARTS			:	<u>\$ 17,598.00</u>	

11308

# Premium Automobiles

35 Ubi Road 1, Singapore 408699  
Tel: 0366 2323 Fax: 0641 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 74781

S/N	Parts Description	Damaged Parts & Prices S/Nett	Remarks
101	CENTRAL PROTECTION X /NI	\$ 500.00	
102	FRONT NO PLATE / BT	S/N \$ 40.00 /	
103	REAR NO PLATE / BT	S/N \$ 40.00 /	
104	ACRYLIC SEALANT / MC	S/N \$ 360.00 /	
105	CAVITY WAX / MC	S/N \$ 280.00 /	
106	STONE CHIP / MC	S/N \$ 360.00 /	
107	METAL FILLER POWDER / MC	S/N \$ 280.00 /	
108	REAR WINDSCREEN SEALANT / MC	S/N \$ 200.00 /	
109	BOTH 1/4 GLASS SEALANT / MC	S/N \$ 200.00 /	
110	SUNDRIES ? / MC	\$ 1,000.00	249-76 /
TOTAL SPARE PARTS		: \$ 63,199.00	
TOTAL LABOUR CHARGES		: \$ 46,624.00	
GRAND TOTAL		: \$ 109,823.00	
		1760	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

134,924.08#

~~total parts 25056~~  
 total parts 25176  
~~total labour 14312~~  
 total labour 14312  
~~given 39488~~  
 given 39488