



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLT 3476 T

*NOT Authorized
Resurvey Bypaint*

Parts	(a) Cost / List Price Items	\$ 4,007.87
	Plus/Less 25%	\$ 1,001.97
	Total of Cost / List	\$ 3,005.90
	(b) Nett Price Items	
	Less	
	Total of Nett Item	
	(c) Special Nett Items	
Total Parts Cost		\$ 3,005.90
Labour		\$ 2,100.00
Total		\$ 5,105.90

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kennerly

Company

CLC

Survey conducted on

25/8/20

at *10:15*

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : *05* day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLT 3476 T**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU103574801**

Submit By : **SERENCE**
Year Manufacture : **Oct-17**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front door	1	\$1,121.75		✓
2	LH front door hinge top	1	\$78.30		X
3	LH front door hinge bottom	1	\$78.30		✓
4	LH front door weatherstip	1	\$211.69		X
5	LHF door glass outer moulding	1	\$121.75		X
6	LH rear door	1	\$1,211.40		✓
7	LH rear door hinge top	1	\$78.34		X
8	LH rear door hinge bottom	1	\$78.34		X
9	LH rear door weatherstip	1	\$198.70		✓
10	LHR door glass outer moulding	1	\$107.80		X
11	LH side skirt	1	\$721.50		X
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

