



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg Nq.: 201939168R

Model : AUDI Q5

Veh No: SJZ2961H

Qty	List Items	Amount S\$
1	FRONT BUMPER <i>1 X R</i>	2326 X
1	FRONT GRILLE <i>/ CUT</i>	1174 /
1	FRONT LOGO <i>/ ML</i>	150 /
2	FRONT BUMPER RETAINERS @ 118 <i>/ BR</i>	236 /
1	FRONT FOAM FILLER X <i>NM</i>	95 X
1	FRONT REINFORCEMENT X <i>NM</i>	882 X
2	FRONT SENSOR @ 196 X <i>NM</i>	392 X
Sub Total		5255
Less 5%		262.75
		4992.25

*1560
- 5%
1482*

Qty	Special Nett Items	Amount S\$
1	FRONT NUMBER PLATE <i>/ BR</i>	60 /
1	FRONT NUMBER PLATE CASING <i>/ CUT</i>	60 30
1 SET	FRONT BUMPER CLIPS <i>/ ML</i>	80 30
1 SET	FRONT GRILLE CLIPS <i>/ ML</i>	70 30
Sub Total		270

140

Qty	Labour charges	Amount S\$
1	CHECK AND RECTIFY FRONT ELECTRICAL WIRING	250 30
1	REMOVE AND REPLACE FRONT SENSORS	200 30
1	TUFFKOTE	250 30
1	TO PUTTY, SPRAY PAINT ETC	1500 250
1	TO PANEL BEAT, WELD, ALIGN, REFIX ETC	1600 300
Sub Total		3800

640

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$ 9062.25

*Steve (LKK) w/ ML PNL
4/6/20, 1.30pm
L/S
Ry AL M
2 days*

*P - 1482
M - 140
L - 640 = 2264*

*L/S - 1899.69
= 1890*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: