Shirley Hiew (LKK Auto)

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAuto) Wednesday, 10 June 2020 9:44 am Sent: To: Shirley Hiew (LKK Auto) Subject: Re: SMP 4165T DOA - 19/05/2020 Hi Shirley, Audit check done for SMP4165T found quoted repair range is fine, 5 repair days should be fine. Best Regards, **Simon Ho** LKK Auto Consultants Pte Ltd Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth· Print only when necessary· From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> Sent: Wednesday, 10 June 2020 9:23 AM To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com> **Subject:** RE: SMP 4165T DOA - 19/05/2020 Hi Simon, As spoken, please refer to the attached. Thank you. Best Regards, Shirley Hiew | Case Handler **LKK Auto Consultants Pte Ltd**

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Shirley Hiew (LKK Auto)

Sent: Wednesday, 10 June 2020 8:47 am

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: SMP 4165T DOA - 19/05/2020

Hi Simon,

Please refer to the attached.

Kindly check the PRS report and let me know whether can I submit this report.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.