

100 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 4175

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GBH1574M

Accident Date : 3/6/2020

Location : ANG MO KIO AVE 3

Steve (LKK) *mm*
8322 8813

5/6/20, 3.00pm
L/S
My AL sy, 5 dys

Model:

TOYOTA HIACE
(11/5/2018)

3P:

SLZ7617X (China Taiping)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper / <i>OR</i>	-	-	596.20
2	1 pc	Rear bumper n/s retainer clips / <i>OR</i>	-	-	182.70
3	10 pcs	Rear bumper clips / <i>MC</i>	-	30.00	-
4	1 pc	Rear bumper n/s top garnish / <i>DEF</i>	-	-	154.20
5	1 pc	Rear n/s tail-lamp / <i>CH</i>	-	-	654.20
6	1 pc	Rear tail-gate X <i>R</i>	-	-	1,925.90
7	1 pc	Rear tail-gate weatherstrip X <i>N/A</i>	-	-	420.00
8	1 pc	Rear tail-gate emblem <i>MC</i> / <i>MC</i>	-	-	62.00
9	1 pc	Rear end panel <i>MC</i> X <i>R</i>	-	-	596.00
10	1 pc	Rear windscreen inner seal X <i>N/A</i>	-	-	196.00
11	1 pc	Rear tail-gate 70 KMPH emblem / <i>MC</i>	-	15.00	-
12	1 pc	Rear tail-gate haice emblem / <i>MC</i>	-	58.90	-
13	1 pc	Rear n/s fender / <i>MC</i>	-	-	2,854.50
Sub-Total:			0.00	103.90	7,641.70
			25%	0%	<i>25 10%</i>
After Less %:			0.00	103.90	6,877.53
Labour					
1		To dismantle damaged parts, straighten & welding.	1,000.00	<i>800</i>	-
2		To spray painting.	800.00	<i>600</i>	-
3		To remove & refit rear windscreen	180.00	X	-
4		To check wiring.	100.00	<i>30</i>	-
5		To re-seal anti-rust.	100.00	<i>30</i>	-
Sub-Total:				2,180.00	-
Total:				9,161.43	-
After Less 20%:				7,329.14	-


Labour - 1460

Nett - 193.90

2827.10
- 25%

Parts - 2129.32

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: GBH1574M ESTIMATEPg1

Mobil 1



PAYNOW

Total - 3684.22
L/S - 2947.37
= 2950