

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJL6167G
Accident Date : 01-Jun-2020

No. : 06175

Date : 03-Jun-2020

Our Ref : 020055 (CHINA) / CHAN

PAGE : 1

KOH PIAH BOH
BLK 250 BISHAN STREET 22
#08-394
Singapore 570250

Not Withhold

1 Day &

Resurvey After Paint

4-9 days

ESTIMATED COST OF REPAIR FOR TOYOTA PRIUS C HYBRID 1.5 SKE1722L

1 pc	Rear bumper fascia		CM 503.10	✓
1 pc	Rear bumper reinforcement		B1 648.90	✓
2 pcs	Rear bumper bracket	@ S\$139.70	B1/D1 279.40	✓
2 pcs	Rear bumper side seal	@ S\$ 97.60	SM 195.20	X
2 pcs	Rear bumper side retainer	@ S\$ 81.70	SM 163.40	✓
1 pc	Tail gate		B1 1,076.10	✓
1 pc	Tail gate "PRIUS C" emblem		SM 59.40	✓
1 pc	Tail gate "TOYOTA" emblem		SM 51.30	✓
1 pc	Tail gate logo		SM 54.80	✓
1 pc	Tail gate "HYBRID" plate		SM 77.40	✓
1 pc	Rear end panel		R 595.80	X
1 pc	End panel top garnish		SM 208.50	X
2 pcs	Taillamp lower bracket	@ S\$ 53.80	SM 107.60	X
			4,020.90	
			Less 25% :	1,005.23

- 1 pc Rear bumper lower spoiler
- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper reverse sensor(set

3,015.67
B1/D1 450.00 sn ✓
SM 60.00 sn ✓
CM 300.00 sn ✓
2001a

To remove & refix rear windscreen glass and conduct water leak test.

150.00 *120*

To remove roof lining, front and rear seats, trim board and carpet

120.00 *50*

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJL6167G

Page : 2

To apply undersealing

80.00 *30/-*

To putty and spray replaced parts

900.00 *720/-*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00 *500/-*

Total : S\$ 5,875.67
=====

Singapore Dollars Five Thousand Eight Hundred
and Seventy Five and Cents Sixty Seven Only