

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 36390

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/401/2020/NS
Date : 28-May-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

3 days - ok - jb - 12 Jul 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Ng Seok Lay
Address : 34 SPRINGSIDE PLACE
Singapore 786437
Telephone : HP +65 96715775
Type of Claim : Own Damage Claims
Policy No. : 2070008660
Vehicle No : **SDF 710 E**
Model Code : Audi Q3 1.4 TFSI S TONIC
Model / Year : 21/12020
Engine No : CZD 887077
Chassis No : WAUZZZF34L1024994
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-May-20
Place of Accident : 34 Springside Place

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDF 710 E

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.		\$ 1,200.00	\$ 500.00
3	To respray rear bumper.		\$ 1,000.00	\$ 550.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 2,752.00</u>	<u>\$ 1,602.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDF 710 E

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	Remarks	
1	REAR BUMPER	\$ 1,397.00	\$	1,117.60
2	REAR BUMPER FIXING PARTS	TBC		
3	REAR BUMPER SPOILER	\$ 433.00	\$	346.40
4	TOWING EYE COVER	\$ 41.00		
5	REAR BUMPER CROSS REINFORCEMENT - CENTRE	\$ 91.00		
6	CLIP	5 \$ 24.00		
7	REAR BUMPER BRACKET	\$ 45.00		
8	REAR LIGHT REFLECTOR - RH	\$ 39.00		
9	REAR PARKING AID SENSOR	TBC		
10	REAR PARKING AID SEAL RING	4 \$ 14.00		
11	REAR WHEEL COVER - LH / RH	2 \$ 506.00	\$	404.80
12	SUNDRIES	\$ 300.00		
TOTAL SPARE PARTS CHARGES		: \$ 2,890.00	\$	1,868.80
TOTAL LABOUR CHARGES		: \$ 2,752.00	\$	1,602.00
GRAND TOTAL		: \$ 5,642.00	\$	3,470.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant