

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NOVA DIAGNOSTICS PTE LTD
28 SENANG CRESCENT #03-12
SINGAPORE 416601

Contact : 88792980

TP China.
Deise.

ESTIMATE

Repair Code : CLM16263

Date in : 03/06/2020

Vehicle Num. : GBB7281A

Model : VOLKSWAGEN CADDY 1.9 TDI

Chassis/Eng# : WV1ZZZ2KZAX012213/BLSA81394

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Defend</i>	1	1488.60	<i>788</i> ✓ 1,488.60
REAR BUMPER REINFORCEMENT <i>Best</i>	1	600.71	✓ 600.71
REAR BUMPER SIDE RETAINER L/R <i>me</i>	2	118.77	✓ 237.54
REAR BUMPER TOW HOOK COVER <i>at</i>	1	130.77	✓ 130.77
REAR END PANEL <i>Regi</i>	1	1167.70	<i>x</i> 1,167.70
REAR END PANEL TOP GARNISH <i>new</i>	1	199.71	<i>x</i> 199.71
REAR END PANEL WEATHER STRIP <i>new</i>	1	300.71	<i>x</i> 300.71
REAR LH DOOR <i>Dented.</i>	1	2339.70	<i>1890</i> <i>2,339.70</i>
REAR LH DOOR 'CADDY' EMBLEM <i>new</i>	1	600.97	<i>65</i> <i>600.97</i>
REAR LH DOOR HINGE (BOTTOM) <i>new</i>	1	188.60	<i>x</i> 188.60
REAR LH DOOR HINGE (TOP) <i>new</i>	1	169.79	<i>x</i> 169.79
REAR LH DOOR MECHANISM LOCK (BOTTOM) <i>Dented</i>	1	366.75	✓ 366.75
REAR LH DOOR NUMBER PLATE LAMP L/R <i>new</i>	2	90.97	<i>x</i> 181.94
REAR LH DOOR OUTER HANDLE <i>at</i>	1	300.75	✓ 300.75
REAR LH DOOR WIPER ARM <i>at</i>	1	67.75	✓ 67.75
REAR LH DOOR WIPER ARM COVER <i>at</i>	1	60.54	✓ 60.54
REAR LH DOOR WIPER MOTOR <i>Damaged</i>	1	375.93	✓ 375.93
REAR LH TAILLAMP <i>at</i>	1	488.67	<i>288</i> <i>488.67</i>

*** This is a computer-generated document which requires no signature.***

TN-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

NOVA DIAGNOSTICS PTE LTD

28 SENANG CRESCENT #03-12

SINGAPORE 416601

Contact : 88792980

ESTIMATE

Repair Code : CLM16263

Date in : 03/06/2020

Vehicle Num. : GBB7281A

Model : VOLKSWAGEN CADDY 1.9 TDI

Chassis/Eng# : WV1ZZZ2KZAX012213/BLSA81394

REAR RH DOOR <i>Dented</i>	1	2339.70	<i>1890</i>	<i>2,339.70</i>
REAR RH DOOR 'LOGO' EMBLEM <i>3 New</i>	1	149.75	✓	149.75
REAR RH DOOR 'TDI' EMBLEM	1	160.77	✓	160.77
REAR RH DOOR HINGE (BOTTOM) <i>New</i>	1	186.77	+	186.77
REAR RH DOOR INNER LOCK OPENER <i>New</i>	1	189.01	+	189.01
REAR RH DOOR MECHANISM LOCK (BOTTOM) <i>Dented</i>	1	333.71	✓	333.71
REAR RH DOOR WEATHER STRIP (SIDE) <i>Replaced</i>	1	369.70	✓	369.70
REAR RH DOOR WINDSCREEN INNER SEAL <i>New</i>	1	180.92	✓	180.92

Subtotal before discount

13,177.46

Percentage discount 5%

658.87

Sub-total 1

12,518.59

REAR BUMPER CLIPS - SET <i>New</i>	1	50.00	<i>30</i>	<i>50.00</i>
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	350.00	<i>200</i>	<i>350.00</i>
REAR END PANEL TOP GARNISH CLIPS - SET <i>New</i>	1	40.00	+	40.00
REAR LH DOOR '70KM' STICKER <i>New</i>	1	25.00	<i>10</i>	<i>25.00</i>
REAR LH DOOR NUMBER PLATE <i>New</i>	1	25.00	+	25.00
REAR LH DOOR NUMBER PLATE HOLDER <i>New</i>	1	50.00	+	50.00
REAR LH DOOR WINDSCREEN INNER SEAL <i>New</i>	1	80.00	<i>40</i>	<i>80.00</i>

*** This is a computer-generated document which requires no signature.***

NOVA-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NOVA DIAGNOSTICS PTE LTD
28 SENANG CRESCENT #03-12
SINGAPORE 416601

Contact : 88792980

ESTIMATE

Repair Code : CLM16263

Date in : 03/06/2020

Vehicle Num. : GBB7281A

Model : VOLKSWAGEN CADDY 1.9 TDI

Chassis/Eng# : WV1ZZZ2KZAX012213/BLSA81394

REAR LH DOOR WINDSCREEN SEALANT	Nu	1	80.00	40.00	80.00
REAR LH TAILLAMP CLIPS - SET	Nu	1	50.00	10.00	50.00
REAR RH DOOR '6PAX' STICKER	Nu	1	25.00	10.00	25.00
REAR RH DOOR WINDSCREEN SEALANT	Nu	1	80.00	40.00	80.00
Subtotal before discount					855.00
Percentage discount			0%		0.00
Sub-total 2					855.00
Parts-total					13,373.59

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,700.00
Parts & Labour Total	16,073.59

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
L/S 05/06/20

06 Days

Total: 872376

L/S: 5K (Nett Value)