



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT20001668	Page	1
Registration No	: SMS3585E	Date	: 18. May 2020	Customer No.	: WZC008
Chassis No	: MRHGM6660LT000193	Svc Advisor	: RUEBEN THOMAS	Engine No	: L15Z16933762
Model	: CITY 1.5SV CVT 2020 (EURO 6)	Date Time	: 18. May 2020 5:13:41 PM	Surveyor Name	:
Owner's Name	: NUR ZAMARINA BINTE JAMALLUDIN	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 17/5/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NUR ZAMARINA BINTE JAMALLUDIN OWNER INSURER: TOKIO MARINE ACC DATE: 17/05/2020 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING INSURANCE TP VEH: SJW5507H						
BO-NUM-COMP-OPC-L	NUMBER PLATE WITH CASING OPC-L	1	45.00		45.00	3.15	48.15
71101-T9A-T20ZZ	FACE, FR. BUMPER	1	459.80	5	436.81	30.58	467.39
91505-TM8-003	CLIP, BUMPER	15	2.30	5	32.77	2.29	35.06
71198-T9A-T00	SPACERL.FR.BUMPER SIDE	1	10.40	5	9.88	0.69	10.57
71193-T9A-T00	SPACERR.FR.BUMPER SIDE	1	10.40	5	9.88	0.69	10.57
71130-T9A-T00ZZ	BEAM COMPFR.BUMPER	1	265.60	5	252.32	17.66	269.98
					Sum Item	786.66	55.06
							841.72
BO-NUM-SEAL	SEAL NUMBER PLATE.	1	80.00		80.00	5.60	85.60
					Sum Ext. Service	80.00	5.60
							85.60
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BML01	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00		100.00	7.00	107.00
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1400.00		1400.00	98.00	1498.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1200.00		1200.00	84.00	1284.00
					Sum Labor	2750.00	192.50
							2,942.50

Survey By _____

Printed on 18/5/2020 5:19:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer :	CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No. :	SQT20001668	Page	2
Registration No :	SMS3585E	Date :	18. May 2020		
Chassis No :	MRHGM6660LT000193	Customer No. :	WZC008		
Model :	CITY 1.5SV CVT 2020 (EURO 6)	Svc Advisor :	RUEBEN THOMAS		
Owner's Name :	NUR ZAMARINA BINTE JAMALLUDIN	Engine No :	L15Z16933762		
Ins Policy No. :		Date Time :	18. May 2020 5:13:41 PM		
Date of Accident :	17/5/2020	Surveyor Name :			
		Survey Date :			
		Authorisation Date :			

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Includ GST	
Date & Time	8/6/20 @ 9am.				Total Amount	3,616.66	253.16	3,869.82
Excess					Total (Inclusive of GST)			<u>3,869.82</u>
Status	not Authorized							
Signature	with take photo before painting							

3 days.

9/7 \$1864.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 18/5/2020 5:19:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

17/6/2020.

PAGE 1/1



© SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

ATTN: MARCUS.

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WO: 3 PAGES.

Customer:	CU0131637 / CHINA TAIPING	Document No:	SVO20025185
Chassis No:	MRHGM6660LT000193	Printed By:	JESHURUEBEN
License No:	SMS3585E	Order Date:	8. June 2020
Mileage:	3558	Order Time:	3:00:42 PM
Engine No:	L15Z16933762	Service Advisor:	RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incld GST
	TP DIRECT SETTLEMENT (J/NO: 74697) OWNER: NUR ZAMARINA BINTE JAMALLUDIN OWNER INSURER: TOKIO MARINE ACC DATE: 17/05/2020 SURVEYED BY: MARCUS (LKK) DATE: 08/06/2020 REF NO: SNM20D201936 TP INSURER: CHINA TAIPING INSURANCE TP VEH: SJW5507H						
BO-NUM-COMP-OPC-L	NUMBER PLATE WITH CASING-OPC-L	1	45.00		45.00	3.15	48.15
71101-T9A-T20ZZ	FACE, FR. BUMPER	1	459.80	5	436.81	30.58	467.39
91505-TM8-003	CLIP, BUMPER	15	2.30	5	32.77	2.29	35.06
	SUM PARTS:				514.58	36.02	550.60
BOSUN	0672 SUNDRIES	1	20.00		20.00	1.40	21.40
BML01I	EXT-YJ INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	80.00		80.00	5.60	85.60
BKBH01S	EXT-YJ STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	650.00		650.00	45.50	695.50
BP02R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)	1	520.00		520.00	36.40	556.40
	SUM LABOUR:				1,270.00	88.90	1,358.90
BO-NUM-SEAL	SEAL NUMBER PLATE.	1	80.00		80.00	5.60	85.60
	SUM EXT SERVICE:				80.00	5.60	85.60
	TOTAL SGD				1,864.58	130.52	1,995.10
	Total Payable (SGD)						1,995.10

GST Amount is calculated from individual line(s)