



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2004892
INV Date 13/07/2020
Reference CC4/EQI20006148/R1pa3s2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SBS 6365J
Insured Veh. GBF 1566Y
Claim No. DM20HO00865-JG
Policy No. DMCPHQ19-003401
Accident Date 29/05/2020
Inspection Date 04/06/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI20006148/R1pa3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Date : 13-07-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 1566Y	Veh. Inspected	SBS 6365J
Policy No.	DMCPHQ19-003401	Coverage (\$)	0.00
Claim No.	DM20HO00865-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	04/06/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CITARO 6.4	c.c	6374
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WEB62808323124770	Colour	GREEN
Odometer	417770	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	MICHELIN	8 mm
L/H Front Tyre	275/70 R22.5	MICHELIN	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	MICHELIN	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	MICHELIN	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/05/2020	Inspection Date	04/06/2020
Survey held at	TOWER TRANSIT SINGAPORE PTE. LTD. 21 BULIM DRIVE SINGAPORE 648170		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 6365J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	NSF BUMPER	CRACKED	1,207.00	1,207.00
1	HEADLAMP LH	SCRATCHED	585.04	585.04
1	NS BLINKER / SIGNAL LAMP	BROKEN	88.06	88.06
1	BUMPER LOCK	BENT	40.18	40.18
1	N/S FRONT BUMPER SPRING LOCK	NECESSARY	19.00	19.00
1	NS EXTERIOR COVERING	NOT NECESSARY	381.46	-
1	FRONT WINDSCREEN GLASS	CRACKED	1,270.00	1,270.00
5	SIKAFLEX BLACK	NECESSARY	80.00	80.00
			3,670.74	3,289.28
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGED PARTS.		6,500.00	1,300.00
	TO PERFORM VEHICLE ALIGNMENT CHECK.	NOT NECESSARY	650.00	-
	SPRAY PAINTING.		2,560.00	640.00
			9,710.00	1,940.00
	GRAND TOTAL		13,380.74	5,229.28
	RECOMMENDED COST OF REPAIRS			5,229.28

Report Ref No. CC4/EQI20006148/R1pa3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBS 6365J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBS 6365J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

