

Ace Auto Solution
 Registration number : 53228991M
 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 4/6/2020

Reference: SLT3107J
 Make: OPEL / ADAM
 1.4 AT

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLT3107J
 CHASSIS NO.: W0L0MAP08H6006456
 ENGINE NO.: B14XER19NU4672

Name of insured : Alpine Car Rental Pte Ltd
 Date of accident: 21/12/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Rear Tailgate <i>Defect</i>	\$ 1,538.00
2	1	Rear Windscreen With Moulding <i>new</i>	\$ 1,032.00
3	1	Rear Tailgate Hinge - RH <i>3 new</i>	\$ 70.00
4	1	Rear Tailgate Hinge - LH	\$ 70.00
5	1	Rear Tailgate Striker <i>3 new</i>	\$ 25.00
6	1	Rear Tailgate Latch	\$ 265.00
7	1	LHR Taillamp <i>3 new</i>	\$ 461.00
8	1	RHR Taillamp	\$ 461.00
9	1	Rear Bumper Upper <i>Defect</i>	\$ 1,450.00
10	1	Rear Bumper Lower - Extension <i>Regis</i>	\$ 931.00
11	1	Rear Bumper Number Plate Lamp <i>new</i>	\$ 30.00
12	1	Rear Bumper Reinforcement Bar <i>new sent</i>	\$ 460.00
13	1	Rear End Panel <i>Regis</i>	\$ 387.00
14	1	LHR Bumper Bracket - Guide outer <i>new</i>	\$ 65.00
15	1	RHR Bumper Bracket - Guide outer <i>new</i>	\$ 65.00
16	1	LHR Bumper Bracket - Guide inner <i>new</i>	\$ 65.00
17	1	RHR Bumper Bracket - Guide inner <i>new</i>	\$ 65.00
18	1	Rear Bumper Bracket - Guide centre <i>new</i>	\$ 75.00

3448
3103.20

Parts Total: \$ 7,515.00
Less 10%: \$ 751.50
Total: \$ 6,763.50

Labour

No.	Labour Description	Price (SGD)
Rear portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 800.00 ✓
2	Carry out spray painting on accident affected area	\$ 800.00 ✓
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00 ✓
4	To remove and refix reverse sensor and conduct test	\$ 80.00 ✓
5	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00 ✓
6	To conduct water leakage test after repairs of vehicle	\$ 40.00 ✗
7	To apply door sealant to 5th rear door	\$ 80.00 ✗
8	To remove and replace rear tail gate windscreen	\$ 120.00 ✓
1180		Labour Total: \$ 2,030.00

Others


Other Description			Price (SGD)
No.	Qty		
Rear portion			
1	1	Rear number plate <i>renew</i>	\$ 45.00 ✓
2	10	Rear bumper clip <i>new</i>	\$ 65.00 ✓
3	5	Rear end panel trim clip <i>new</i>	\$ 32.50 ✗
4	1	Reverse sensor (1 set) <i>new</i>	\$ 360.00 ✗
5	1	Rear reverse camera <i>new</i>	\$ 280.00 ✗
6	1	Rear end panel insulation seal <i>new</i>	\$ 120.00 ✗
7	8	Tail gate inner trim board clip <i>new</i>	\$ 52.00 ✗
8	1	Tailgate windscreen sealant <i>new</i>	\$ 120.00 ✓
9	1	Tailgate windscreen solar film <i>new</i>	\$ 180.00 ✗
135			Other Total: \$ 1,254.50

GRAND TOTAL: \$ 10,048.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU

BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

ours faithfully


Service Advisor
Suhaimi
HP : 9189 2617 Email - aceautosolution@gmail.com

APPROVER DETAILS

SURVEYOR : _____

CONTACT NO : _____

PART BY PART / LUMP SUM

Adrian L
h/s 04/06/20
04 Rep
total: 4418.00
h/s: 3.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Invoice

Ace Auto Solution

Registration number 53228991M

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

INVOICE

To : AIG Asia Pacific Insurance Pte. Ltd
78 SHENTON WAY

#07-16

SINGAPORE 079120

Invoice No. ACC-2015001

Invoice Date:

Vehicle No: SLT3107J
Chasis No : W0L0MAP08H6006456
Engine No: B14XER19NU4672

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.		Price (SGD)
1	1	Rear Tailgate	\$ 1,538.00
2	1	Rear Bumper Upper	\$ 1,450.00
3	1	Rear Bumper Reinforcement Bar	\$ 460.00

Total: \$ 3,448.00

Less 10%: \$ 344.80

Parts Total : \$ 3,103.20

Labour

No.		Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 400.00
2	Carry out spray painting on accident affected area	\$ 500.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
4	To remove and refix reverse sensor and conduct test	\$ 50.00
5	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00
6	To remove and replace rear tail gate windscreen	\$ 120.00

Labour Total : \$ 1,180.00

Other

No.			Price (SGD)
1	1	Rear number plate	\$ 45.00
2	10	Rear bumper clip	\$ 30.00
3	1	Tailgate windscreen sealant	\$ 60.00

Other Total : \$ 135.00

Total : \$ 4,418.20

Less lump sum 20%: \$ 883.64

Grand Total: \$ 3,500.00

Yours Faithfully,



Suhaimi
Service Executive
Tel: 9189 2617 Fax: 6844 5185
Email : aceautosolution@gmail.com

E & O E

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "ACE AUTO SOLUTION".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice