



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



### TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2003216  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSE  
SINGAPORE 189556

INV Date 24/06/2020  
Reference NS/INC20006161/Fsf3n2  
Code INC4



### PROFESSIONAL SERVICE FEE

Vehicle No. SH 7335X  
Insured Veh. SHC 6281E  
Claim No. MT/1093812-002  
Policy No. 5107202885-01  
Accident Date 05/06/2020  
Inspection Date 05/06/2020

| Description         | Total         |
|---------------------|---------------|
| Survey Inspection   | 160.00        |
| Resurvey Inspection |               |
| Digital Photographs |               |
| Transportation      |               |
| <b>Subtotal</b>     | <b>160.00</b> |
| <b>GST (7%)</b>     | <b>11.20</b>  |
| <b>Grand Total</b>  | <b>171.20</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

National Assessment Centre Services

*HYN*




## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



|  |  |                 |                    |   |
|--|--|-----------------|--------------------|---|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20006161/Fsf3n2      |  |                 |                    |   |
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556 |  |                 | Date: 24-06-2020   |  |
| Code: INC4   |  |                 |                    |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                      |  |                 |                    |   |
| Insured Veh.   | SHC 6281E  | Veh. Inspected  | SH 7335X           |   |
| Policy No.   | 5107202885-01  | Coverage (\$)   | 0.00               |   |
| Claim No.  | MT/1093812-002   | Excess (\$)     | 0.00               |   |
| Assign From  |  | Assign Date     | 05/06/2020         |   |
| <b>2. Vehicle Particulars &amp; Condition</b>                          |  |                 |                    |   |
| Make & Model   | HYUNDAI I40  | c.c             | 1685               |   |
| Engine No.   | HIDDEN   | Year of Reg.    | 2017               |   |
| Chassis No.  | KMHLB41UMHU098583  | Colour          | BLUE               |   |
| Odometer   | 425325   | Steering        | IN ORDER           |   |
| Brakes   | IN ORDER   | Modification    | STANDARD ALLOY RIM |   |
| General  | FAIR   |                 |                    |   |
| <b>3. Conditions of Tyres</b>  |  |                 |                    |   |
|  | Size   | Make            | Balance            |   |
| R/H Front Tyre   | 205/60 R16   | DURATURN        | 6 mm               |   |
| L/H Front Tyre   | 205/60 R16   | DURATURN        | 6 mm               |   |
| R/H Rear Tyre  | 205/60 R16   | DURATURN        | 7 mm               |   |
| L/H Rear Tyre  | 205/60 R16   | DURATURN        | 7 mm               |   |
| <b>4. Description of Damages</b>                                       |  |                 |                    |   |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |                 |                    |   |
| <b>5. General Information</b>  |  |                 |                    |   |
| Accident Date  | 05/06/2020   | Inspection Date | 05/06/2020         |   |
| Survey held at   | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969   |                 |                    |   |
| <b>5a. Remarks</b>   |  |                 |                    |   |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                 |                    |   |
| <b>5b. Estimate Days of Repair</b>                                     |  |                 |                    |   |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: <b>2 Working Days</b>  |                 |                    |   |

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7335X**

| Qty | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                          |                      |                           |                   |
| 1   | REAR BUMPER COVER   | TO REPAIR SEE LABOUR | 1,106.00                  | -                 |
| 2   | REAR BUMPER BRACKET SIDE LH/RH @\$35.60                     | NOT NECESSARY        | 71.20                     | -                 |
| 10  | REAR BUMPER CLIPS @\$2.20                                   | NOT NECESSARY        | 22.00                     | -                 |
|     | LESS 20% DISCOUNT   |                      | -239.84                   | -                 |
|     |   |                      | 959.36                    | -                 |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                            |                      |                           |                   |
| 1   | REVERSE SENSOR (SN)   | NOT NECESSARY        | 135.70                    | -                 |
| 1   | REAR BUMPER MAT (SN)  | NOT NECESSARY        | 50.00                     | -                 |
|     |   |                      | 185.70                    | -                 |
|     | <b><u>LABOUR</u></b>  |                      |                           |                   |
|     | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER COVER. |                      | 280.00                    | 280.00            |
|     | SPRAY PAINTING CHARGE.                                      |                      | 400.00                    | 200.00            |
|     | REMOVE/REFIX REVERSE SENSOR.                                | NOT NECESSARY        | 60.00                     | -                 |
|     | TUFF KOTE.  | NOT NECESSARY        | 60.00                     | -                 |
|     | CHECK LIGHTING.   | NOT NECESSARY        | 60.00                     | -                 |
|     |   |                      | 860.00                    | 480.00            |
|     | <b>GRAND TOTAL</b>  |                      | <b>2,005.06</b>           | <b>480.00</b>     |
|     | <b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>              |                      |                           | <b>480.00</b>     |

Report Ref No. NS/INC20006161/Fsf3n2


**PARASURAM S/O SHANMUGAM**

Asst. Automotive Assessor


**K.K.LAU CPT(RET)**
**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**
**REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## National Assessment Centre Services


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SH 7335X

INSPECTION





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SH 7335X

RE-INSPECTION

