

# S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 16th June 2020

To : LKK

Attn : Bryan

Tel :

By Fax:

VEHICLE NO : FBR 3732H

Yamaha N Max 155

ACCIDENT DATE: 9th June 2020

	Description	Qty	Quotation \$
1	Head Lamp Assembly <i>Scratched</i>	1	550.00 ✓
2	LH side panel lower white <i>van</i>	1	260.00 X
3	LH Front side lamp <i>Scratched</i>	1	155.00 ✓

Sub-Total 965.00

Less 10% 96.50

Sub-Total 868.50

VEHICLE NO : FBR 3732H

Yamaha N Max 155

## Nett items

- 1 Remove & replace above parts,  
align & etc

220.00

*280.00 180/-*

Sub-Total 220.00

Nett Total 1,088.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion  
Thank you

S9 TRADING PTE LTD

*12/06/2020 @ 1700hrs*

*Not Author*

*L/Same 1 day*

*you*

*LKK Auto*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: