趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047 Tel: 6484 1626 (24Hrs) Fax: 6484 0465 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO Not Nothersel Presure, BEPaint Edan

Third Party

To:	AIG Asia Pacific Insurance Pte Ltd		Policy No:	111101 2119
				09.06.2020
41	Accident Date : 24.05.202	20		
Specialised in	Car Painting, Welding,	ESTIMATE		承接汽车烧焊喷漆及 代理各种车辆赔偿
	and insurance claim.		单价	银 Amount 额
数 量 Quantity		货 名 ESCRIPTION	Unit Price	\$ cts.
1pc 1pc 1pc 1pc 1pc 1pc 1pc 1pc 1pc 1pc	Claiming Against Your In Tailgate Tailgate Emblem Tailgate Sticker Toyota Tailgate Sticker Hiace Tailgate Lock Tailgate Lock Tailgate Trim Board Clips Tailgate Weatherstrip Tailgate Weatherstrip Tailgate Weatherstrip Tailgate Weatherstrip Tailgate Glass Facket Rear Bumper Bracket Rear Bumper Clips End Panel 7 Less 25% Tailgate Glass Sealant Tailgate Glass Sealer Tailgate Glass Fasterner Tailgate Glass Fasterner Tailgate Sticker Tailgate Sticker Tailgate Lower Protector Rear Bumper Reverse Sens Rear Number Plate	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer	New New Short	FOSN 50.00 SN 205N 40.00 SN 305N 50.00 SN Na 18.00 SN/25 Na 50.00 SN Posn 135.00 SN 265N 45.00 SN 255N 45.00 SN
	Rewiring etc	gate Fittings / Ancillary Accessories		120.00 601
	To Dismantle / Refit Tailgate			160.00 1201
4	To Supply End Panel Body Sealant			60.00 7
39	To Apply Rust Proofing / Res / Replaced / Repair Panel Jo	seal Tuff Coating Treatment to Respray int Sealant		120.00 ?
	Labour Charge - Panel Beati Panel, Cnt Weld End Panel a	ng, Repairing Of Rear Floor Plate, End Inn and Parts Replacement	er	950.00 ? 6001
	To Respray Affected Areas		Total:	800.00 2,998.00