

AXA MSICO 7day

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48, AUTO BAY
SINGAPORE 417883

VEHICLE No: SKC 9399U

not Authorised
HWH
8/6/20
2/5 \$6000/
5 days.
Take photo After repair

1PC	REAR WINDSCREEN MOULDING	
1PC	TAILGATE	1755.10
1PC	TAILGATE REAR LOGO	
1PC	TAILGATE 'ALPHARD' EMBLEM	
1PC	TAILGATE INNER LOCK	
1PC	TAILGATE INNER TRIM	
1PC	TAILGATE WEATHERSTRIP	
1PC	REAR BUMPER	1050.00
2PCS	REAR BUMPER SIDE RETAINERS @\$85.50	
1PC	REAR BUMPER TOW COVER	
1SET	REAR BUMPER CLIPS	
1PC	REAR END PANEL OUTER	
1PC	REAR END PANEL INNER	
1PC	REAR END PANEL TOP GARNISH	
1PC	REAR END PANEL LOCK SENSOR	
1PC	TAILLAMP N/S	
1PC	TAILGATE OUTER CHROME GARNISH	25%

rec	\$128.10	✓
body to	\$2,866.10	✓
rec	\$68.50	✓
rec	\$82.50	✓
FWI/Should	\$509.20	✓
De/To.1	\$661.10	✓
FWI	\$398.50	✓
to/De	\$1,655.10	✓
17	\$171.00	X
17	\$48.50	X
rec	\$50.00	✓
body to	\$788.10	✓
n	\$699.50	X
17	\$388.10	X
CR2	\$385.10	✓
17	\$1,050.20	X
sen/cr2	\$976.20	✓
	\$10,925.80	

S.NETT

1PC	REAR WINDSCREEN SEALANT	
2PCS	REAR BUMPER PDC SENSORS @\$350.00	215 PL = 430
1PC	REAR END PANEL SEALANT	

rec	\$50.00	40
short	\$700.00	430
17	\$50.00	X

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPAIRING PDC SENSOR	\$100.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO SPRAY RUST PROOFING	\$80.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO TRANSFER TAILGATE MECHANISM	\$120.00	60
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$880.00	600
TO PUTTY & SPRAY PAINTING	\$1,500.00	900

TOTAL \$14,755.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-6842.4
252
5139.3
7809.3