

Our Job Ref No : 305403035
Date : 06/10/20

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : TAUFGIH
: SH6091E

Fax :

05/06/20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


- Z The repair job shall bill to: CHINA GBJ2956C
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$1,202.00</u> |
| (b) Labour Charges | <u>\$1,110.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$2,312.00</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs: 4 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : Tanyin
Date : 12/6/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Pls expedite this case. Third party Seeking for mutual Settlement

AKK / ching

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.06.2020

REPAIR ESTIMATE

Time: 12:59:00

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305403035
REGN NO : SH 6091E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.12.2017
DATE/TIME IN : 06.06.2020 10:15
ACCIDENT DATE : 05.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80
0002 04-01-0103-0783-G	I40VC BRKT ASSY-RR BUMPER	1	35.60	20.00	28.48
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0004 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	107.10	20.00	85.68
0005 03-01-0103-0122-G	I40VC GUARD ASSY-RR WHEEL	1	169.30	20.00	135.44
0006 04-01-0103-1150-A	I40VC PROTECTOR MAT	1	50.00	2.00-	50.00

SUB-TOTAL : 1,202.00

JOB NATURE

0000 PB	PANEL BEATING	560.00
0001 SP	SPRAYPAINT CHARGE	400.00
0002 20-22	REMOVE/REFIX REVERSE SENSOR	30.00
0003 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	60.00
0004 20-00	TUFF COAT ON AFFECTED PARTS.	30.00

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 10.06.2020
Time: 12:59:00
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305403035
REGN NO : SH 6091E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.12.2017
DATE/TIME IN : 06.06.2020 10:1
ACCIDENT DATE : 05.06.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0005 17-01	CHECK ALL LIGHTING		30.00		

SUB-TOTAL : 1,110.00

TOTAL : 2,312.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

ESTIMATE*

LE NO

FRANK®

05/06/20

MODEL HYU-140

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

WP'

P/P Resumy before paint
04 days

tanpin @ khand.com.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____

Date: