

COMFORTDELDRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH6091E

05/06/20

MAKE :

MODEL HYU- I40

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		LHX \$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR WHEEL COVER RH			\$107.10
1	REAR RH FENDER			\$2,171.40
1	REAR FENDER INNER LINING RH			\$169.30
	SUB TOTAL			\$3,647.00
	20.00%			\$729.40
	DISCOUNTED TOTAL			\$2,917.60
1	REVERSE SENSOR			\$135.70
1	REAR BUMPER MAT			\$50.00
				\$185.70
	Labour Charge			
	Panel Beating			\$720.00
	Spray Painting Charge			\$500.00
	Remove/refix reverse sensor			\$60.00
	Remove/refix rear upholstery			\$120.00
	Remove/refix rear winscreen			\$120.00
	Tuff Kote			\$60.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$1,640.00
	ESTIMATE TOTAL			\$4,743.30
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Taufik 97495749

WP'

8/6/20 @ 355 pm

P/P Rising before paint

04 days

taufik @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: