STIM! TE*

5H6091E

05/06/20

FIJAKE'

HYU- 140 MODEL

LENO

Qty			CHIANG/CHINA		1
	Parts Description/ Labour	Туре	Unit Price	Amount	1.
	REAR BUMPER COVER	1	4.0	\$1,106.00	
	REAR BUMPER BRACKET SIDE LH/RH		MXN \$35.60	\$71.20	RH-de.
	REAR BUMPER CLIPS		\$2.20	\$22.00	ner
	REAR WHEEL COVER RH			\$107.10	aut -
	REAR RH FENDER			\$2,171.40	RY
	REAR FENDER INNER LINING RH			\$169.30	di
	SUB TOTAL		1440	\$3,647.00	
	20.00%		20% 1152.	\$729.40	
	DISCOUNTED TOTAL		- (\$2,917.60	
					Lan.
l .	1 REVERSE SENSOR			\$135.70	X
	1 REAR BUMPER MAT			\$135.70 \$50.00	14/
			50.	\$185.70	
	Labour Charge				
	Panel Beating			\$720.00	510
	Spray Painting Charge			\$500.00	
	Remove/refix reverse sensor			\$60.00	
.5	Remove/refix rear upholstery			\$120.00	
	Remove/refix rear winscreen			\$120.00	
	Tuff Kote			\$60.00	
	Check Lighting		(110.	\$60.00	100
	TOTAL LABOUR		1152	\$1,640.00	20
				\$2,040.00	1
	ESTIMATE TOTAL		110	\$4,743.30	1
		8	2312 th older		1
1		,	7	1	
	This is an initial estimate based on a visual inspection of th	an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tauful 97495749 el 6 fro e 355 pm P/P Risum byon paint of days faifth e Mantocom.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: