

ASS. REC. BY: Sun Pin.REF: III CCG/II I 20006175/Qba 3

(TP)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA 571J Yr Regn: 25/05/2018.Type: (M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Freed 1.5G. c.c 1496.Colour: Silver. A/C: Insured / Std / NI / NASp. Reading: 162404 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: G871065319.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 195/60 R15R: 195/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake.

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 14/05/2020 D.O.I. 11/06/2020.Survey held at Huat HongDes. of Damages: Frt / Rear (O/S) / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 77,000

PV: 44,791

NV: 32,000

Date/Time, File Pass to? ☐ : Prell. Report1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Form: _____

Lump Sum / L.E. / _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. \$ _____☐ : Interview (\$ _____) Phone _____☐ : Tech. Invs (\$ _____) Others _____☐ : Weekend (\$ _____)

TOTAL

Hua Hong Pte Ltd
25D SUNGKEI KADUT STREET 1
729332

Insurer Reference: ^{H4}
 Repairer Reference: 031822-TP2063
 Date calculated: 11/06/2020 3:10 PM

Full Report
Registration: SMA571J
Printed: 11/06/2020 3:11 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	India International Insurance
Printed by:	Hua Hong	Currency:	SGD
Claim Reference:		Date of Incident:	14/05/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
 Manufacturer: HONDA
 Model: FREED (GB3)
 Sub Model: BASE MODEL
 Model Sheet Number: 35 FD 01
 Registration: SMA571J
 VIN number:
 Odometer:

Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R R/R OUTER DOOR MOULDING		2.0	10.00
NO NUMBER	R + R R/R WHEEL HUB AND WHEEL BEARING		6.0	30.00
9566	R/R TYRE REMOVE AND REFIT		10.0*	50.00
1782	R/R DOOR REPAIR	\$125	25 50.0*	250.00
3482	R/R SIDE PANEL REPAIR	\$125	25 50.0*	250.00
Labour Cost			Hrs	WU
Panel / Mechanical Labour			11.80	118.0
Total of Labour				590.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description		WU	Price SGD
	R/R DOOR REPAIR PAINTING >50%		50 70.0*	\$250
	R/R SIDE PANEL REPAIR PAINTING >50%		50 70.0*	\$250

Paint Material Per Part

Code	Description	Price SGD
1782	R/R DOOR REPAIR PAINTING >50%	22.47

Paint Material Per Part

Code	Description	Price SGD
3482	R/R SIDE PANEL REPAIR PAINTING >50%	21.51

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			140.0	
Total	10 WU/h	14.00	140.0	700.00

Material Cost - Paint

	Price SGD
Repair Painting	43.98
Material-constant Metal	18.10
Total	62.08

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
1948	R/R DOOR MOULDING	72721SYY003	OEM	X SVC	45.00
9182	R/R WHEEL HUB/BRG	42200TF0Z51	OEM	X door SVC	321.00
f: OEM Parts					0.00
n: Non-OEM Parts					366.00
u: Used parts					36.60
Savings					8.05
Subtotal					410.65
Addition(+10.00%)					
Sundry Parts(+2.0%)					
Total					410.65

Extras

Code	Description	Price SGD
1000	REAR SPORT RIM RH SPORT RIM RH	350.00*
1001	4 WHEEL ALIGNMENT WHEEL ALIGNMENT	100.00*
Total Extras		450.00

Final Calculation

	SGD	SGD
Parts	366.00	
Addition(+10.00%)	36.60	
Sundry Parts(+2.0%)	8.05	
Total Parts		410.65
Labour Time Base 10 WU/h		
Total 118.0 WU X 50.00 SGD/h	590.00	
Total of Labour		590.00
Total Of Extras		450.00
Paint Work Time Base 10 WU/h		
Labour Cost 140.0 WU X 50.00 SGD/h	700.00	
Material Cost	62.08	
Total Paint Including Material		762.08
Repair Cost Excludes GST		2,212.73
GST (+7.00%)		154.89
Repair Cost Included GST		2,367.62

P/P = \$ 1,272.08
3 days

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Repair day 3 days

P/P

After paint photo

Sun Pin (LKK)

11/06/2020

TP without prejudice

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hua Hong Pte Ltd
25D SUNGKEI KADUT STREET 1
729332

Insurer Reference:
Repairer Reference: HHTP2063
Date calculated: 12/10/2020 12:47 PM

Full Report
Registration: SMA571J
Printed: 12/10/2020 12:51 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	India International Insurance
Printed by:	Hua Hong	Currency:	SGD
Claim Reference:		Date of Incident:	14/05/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
 Manufacturer: HONDA
 Model: FREED (GB3)
 Sub Model: BASE MODEL
 Model Sheet Number: 35 FD 01
 Registration: SMA571J
 VIN number:
 Odometer:

Labour

		Time Base 10 WU/h	Price = 50.00 SGD/h	
Code	Description		WU	Price SGD
9566	R/R TYRE REMOVE AND REFIT		10.0*	50.00
1782	R/R DOOR REPAIR		25.0*	125.00
3482	R/R SIDE PANEL REPAIR		25.0*	125.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		6.00	60.0	300.00
Total of Labour				300.00

Paint

		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description		WU	Price SGD
	R/R DOOR REPAIR PAINTING >50%		50.0*	
	R/R SIDE PANEL REPAIR PAINTING >50%		50.0*	

Paint Material Per Part

Code	Description	Price SGD
1782	R/R DOOR REPAIR PAINTING >50%	22.47
3482	R/R SIDE PANEL REPAIR PAINTING >50%	21.51

	Hrs	WU	Price SGD
Labour Cost - Paint			
Factor	50.00 SGD/h		
Time Paint		100.0	
Total	10 WU/h	100.0	500.00

	Price SGD
Material Cost - Paint	43.98
Repair Painting	18.10
Material-constant Metal	62.08
Total	

Code	Description	Price SGD
1000	REAR SPORT RIM RH SPORT RIM RH /SCR	350.00*
1001	4 WHEEL ALIGNMENT WHEEL ALIGNMENT /Nec	60.00*
	Total Extras	410.00

	SGD	SGD
Labour Time Base 10 WU/h		
Total 60.0 WU X 50.00 SGD/h	300.00	
Total of Labour		300.00
Total Of Extras		410.00
Paint Work Time Base 10 WU/h		
Labour Cost 100.0 WU X 50.00 SGD/h	500.00	
Material Cost	62.08	
Total Paint Including Material		562.08
Repair Cost Excludes GST		1,272.08
GST (+7.00%)		89.05
Repair Cost Included GST		1,361.13

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

P/P
\$1,272.08
3 days