



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

INV No. AC2103455

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV Date 17/05/2021
Reference CC4/EQI20006176/R1ba3q2
Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 2261R
Insured Veh. SJM 36K
Claim No. DM20HO00891-JG
Policy No. DMPPHQ19-007137
Accident Date 09/06/2020
Inspection Date 29/06/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CC4/EQI20006176/R1ba3q2 Date: 17/05/2021 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJM 36K	Veh. Inspected	SMA 2261R	
Policy No.	DMPPHQ19-007137	Coverage (\$)	0.00	
Claim No.	DM20HO00891-JG	Excess (\$)	0.00	
Assign From	JOEL GOH	Assign Date	12/06/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ATTRAGE 1.2 CVT	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MMBSTA13AJH001687	Colour	GREY	
Odometer	15333 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	185/55 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/06/2020	Inspection Date	29/06/2020	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 2261R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PANEL ASSY,FR DOOR,RH (SN)	BENT	996.00	996.00
1	TAPE,FR DOOR SASH,RH (SN)	NECESSARY	29.00	29.00
1	PANEL ASSY,RR DOOR,RH (SN)	BENT	799.00	799.00
1	TAPE,RR DOOR SASH,RH (SN)	NECESSARY	29.00	29.00
1	UNPAINTED BODYKITS (SN)	SCRATCHED	1,643.00	1,643.00
1	EMBLEM ECO (SN)	NECESSARY	17.00	17.00
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
			3,563.00	3,543.00
	<u>LABOUR</u>			
	RENEW RHS DOOR,RHR DOOR & ROCKER PNL BODY KIT.REPAIR RHF FENDER,RHR FENDER,RR BUMPER & BODY KIT.		3,300.00	2,750.00
	RESPRAY RHF FENDER,RHF DOOR,RHR DOOR,RHR FENDER,RR BUMPER,RR BUMPER BODY KIT & ROCKER PNL BODY KIT LH.		2,520.00	2,520.00
	REMOVE & REFIT RHF DOOR COMPONENT.		275.00	275.00
	REMOVE & REFIT RHR DOOR COMPONENT.		275.00	275.00
	CHECK WIRING ELECTRICAL SYSTEM.		50.00	50.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI SCAN PRO TEST USING HI SCAN PRO TEST.		200.00	200.00
	APPLY ANTI CORROSION ON AFFECTED AREAS.		250.00	150.00
	REMOVE & REFIT REVERSE SENSOR.		100.00	80.00
			6,970.00	6,300.00
	GRAND TOTAL		10,533.00	9,843.00
RECOMMENDED COST OF REPAIRS				9,843.00

Report Ref No. CC4/EQI20006176/R1ba3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 2261R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 2261R

RE-INSPECTION

