

ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 1977014696

Invoice Name & Address

Tham Cheng-e (tan Jingyu)
Blk 55 Strathmore Avenue
#05-147
Singapore 140055
Contact No Mobile: 90114007

Owner Name & Vehicle Info

Cust No/Name	/Tham Cheng-E (Tan Jingyu)
Reg No/Reg Date	SMA2261R / 31/05/201
Date In/Mileage	/ 0
Chassis No	MMBSTA13AJH001687
Engine No	3A92UGR8679
Make/Model	MIT/18MY ATTRAGE 1.2 CVT
Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	10/06/2020/ 10:49	QUE	261 / Edwin Caina	53565		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

- E PNT88000
RENEW RHF DOOR, RHR DOOR & ROCKER PNL BODY KIT
REPAIR RHF FENDER, RHR FENDER, RR BUMPER & BODY KIT
- E PNT98000
RESpray RHF FENDER, RHF DOOR, RHR DOOR, RHR FENDER, RR BUMPER,
RR BUMPER BODY KIT & ROCKER PNL BODY KIT LH,
- E PNT88000
REMOVE & REFIT RHF DOOR COMPONENT
- E PNT88000
REMOVE & REFIT RHR DOOR COMPONENT
- A 54900099
CHECK WIRING ELECTRICAL SYSTEM
- A 10028901
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST
USING HI-SCAN PRO TEST
- M SUNDRY
APPLY ANTI CORROSION ON AFFECTED AREAS
- E PNT88000
REMOVE & REFIT REVERSE SENSOR
- M SUNDRY
Sundries
- M PANEL ASSY,FR DOOR,RH *lt*
- M TAPE,FR DOOR SASH,RH *rec*
- M PANEL ASSY,RR DOOR,RH *lt*
- M TAPE,RR DOOR SASH,RH *rec*
- M UNPAINTED BODYKITS *scr*
- M EMBLEM ECO *rec*

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1.00	996.00	00.00	996.00
1.00	29.00	00.00	29.00
1.00	799.00	00.00	799.00
1.00	29.00	00.00	29.00
1.00	1643.00	00.00	1643.00
1.00	17.00	00.00	17.00

2750 3300.00
2520.00
275.00
275.00
50.00
200.00
150 250.00
80 100.00
30 50.00

SURVEYOR NAME:

SURVEYOR SIGNATURE:

DATE:

P/P = \$ 9,843.00

Confirm & accepted by

REMARKS:

Authorized signatory and company stamp

7% GST on 10533.00 737.31

Nett 10,533.00

Total Payable 11,270.31

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.