

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 8 June 2020

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FX 8629L


Honda CB400 M Spec3

ACCIDENT DATE: 3 June 2020

Description	Qty	Quotation \$
1 Rear Tail Panel <i>broken</i>	1	258.00 ✓
2 Rear Lock <i>bt</i>	1	150.00 ✓
3 Tail Lamp <i>switched/cut</i>	1	178.00 ✓
4 Rear - RH Signal Lamp <i>LH broken</i>	1	125.00 ✓
5 Handle Bar <i>bt</i>	1	195.00 ✓
6 Clutch Level <i>cut</i>	1	95.00 ✓
7 Mirror <i>cut N/S o/s HW</i>	1 set	220.00 ✓ 110.00
8 Shroud L/RH <i>cut N/S o/s HW</i>	2	270.00 ✓ 135.00
9 Crash Bar <i>cut</i>	1 set	330.00 ✓
10 Front Cowling <i>cut</i>	1	285.00 ✓
11 Front Mudguard <i>rg</i>	1	235.00 X
12 Head Lamp <i>HW</i>	1	1,100.00 X
13 Fuel Tank <i>rg</i>	1	350.00 X
Sub-Total		3,791.00
Less 10%		379.10
Sub-Total		3,411.90

1861.00

10% 1674.90



VEHICLE NO : FX 8629L

Honda CB400 M Spec3

Nett Items

- 1 Rear number plate *bt*
- 2 Towing fee *nm*
- 3 Remove & replace parts, align, & etc
- 4 Putty & touch up paint work
- 5 Dismantle & repress fork tube, fork under bracket, labour

25.00 *15/-*

40.00 *X*

250.00 *200/- 220/-*

435.00
~~380.00~~ *200/-*

180.00 *nm*

Sub-Total

775.00

Nett Total

4,286.90

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

S9 MOTOR TRADING PTE LTD

:LG

05/06/2020 1745hrs

NA return

2/3 same 4 days

Yam

2KK Auto

2109.90

4/5 1650/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: