



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM20006181/Aea3q2 Date: 17/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBF 8475E	Veh. Inspected	SMJ 631Y	
Policy No.	P2281363	Coverage (\$)	0.00	
Claim No.	S0M02P34	Excess (\$)	0.00	
Assign From		Assign Date	10/06/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MHFZ28H3000062288	Colour	SILVER	
Odometer	84344 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	DAYTON	6 mm	
L/H Front Tyre	185/60 R15	DAYTON	6 mm	
R/H Rear Tyre	185/60 R15	DAYTON	6 mm	
L/H Rear Tyre	185/60 R15	DAYTON	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/02/2020	Inspection Date	12/06/2020	
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	