

Date : 10/06/2020

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Our Customer : Chew Cheng Chua
Vehicle No : SMJ631Y
Model : Toyota Sienta Standard (Auto)
Manufacture Year : 2019
Date of Accident : 24/02/2020
Total Estimate Repair Days : 9
Total Pages : 2

Attn : Motor Claims Department
Email : motor.survey@axa.com.sg

Re: Repair Estimate For Third Party Claim against FBF8475E

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks from Surveyor
A.	Spare Parts				
1	Front bumper <i>repair</i>	1	<i>repair</i>	<i>\$500</i>	<i>repair</i>
2	Front bumper side retainer LH <i>new</i>	1	\$59.00	\$59.00	<i>+</i>
3	Front bumper top rubber <i>new</i>	1	\$25.00	\$25.00	<i>+</i>
4	Fog lamp garnish LH <i>new</i>	1	\$133.00	\$133.00	<i>+</i>
5	Headlamp LH <i>cut</i>	1	\$935.00	\$935.00	<i>✓</i>
6	Front grille	1			<i>+</i>
7	Front grille garnish <i>new</i>	1			<i>+</i>
8	Front grille "Toyota" logo	1			<i>+</i>
9	Front fender LH <i>dent</i>	1	\$682.00	\$682.00	<i>✓</i>
10	Front door LH <i>dent</i>	1	\$995.00	\$995.00	<i>✓</i>
11	Front door hinges LH <i>new</i>	2	\$95.00	\$190.00	<i>+</i>
12	Front door striker LH <i>new</i>	1	\$118.00	\$118.00	<i>+</i>
13	Front door outer moulding LH <i>new</i>	1	\$105.00	\$105.00	<i>+</i>
14	Front door weatherstrip LH <i>new</i>	1	\$199.00	\$199.00	<i>+</i>
15	Front door sash pillar black sticker LH <i>new</i>	1	\$98.00	\$98.00	<i>✓</i>
16	Side mirror mechanism LH <i>dent</i>	1	\$560.00	\$560.00	<i>✓</i>
17	Side mirror cover LH <i>dent</i>	1	\$75.00	\$75.00	<i>+</i>
18	Support panel <i>new</i>	1	repair	repair	<i>+</i>
19	Rocker panel LH <i>new</i>	1	repair	repair	<i>+</i>
	<i>front door quarter garnish LH</i>		Sub-Total	\$4,174.00	
			Less 25%	\$1,043.50	
			Sub Total 1	\$3,130.50	
A.	Spare Parts (S/Nett)				
1	Sports rim <i>new</i>	1	\$350.00	\$350.00	<i>+</i>
2	Front fender inner shield clip <i>new</i>	10	\$5.00	\$50.00	<i>30</i>
			Sub Total 2	\$400.00	<i>30</i>
			Total for Parts	\$3,530.50	
B.	Labour				
1	To check wiring.			\$60.00	<i>30</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,200.00	<i>600</i>
3	Spray painting all affected parts & areas.			\$1,200.00	<i>700</i>

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks from Surveyor
4	To spray anti-rust undercoat.			\$60.00	-40
5	To remove and refit front door glass LH.			\$100.00	-80
	Total Labour			\$2,620.00	
	Total Repair Cost			\$6,150.50	

1450

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	Adnan S
Contact	96893733
Survey Date	12/06/20
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OS Pays

total: 4351.75

L/s: 3450