

C

REC. BY:

REF:

FCI / 2000 8183 KK

ASSIGNMENT

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Cptins

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR8469S

Yr Regn:

08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Wagon

Make:

Honda Shuttle

c.c

1496

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

76856

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP7

1116133

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

4/6/20

D.O.I.

15/6/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/6 8 2889.76 Cestinas

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

\$130

Transportation:

\$50 X 2 = \$100

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

\$ + RS. \$

: Fines

: Others

\$18

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

\$248

Date: 08.06.2020
 Vehicle No: SLR8469S
 Model: HONDA SHUTTLE HYBRID 1.5A
 Chassis: GP71116133-2017
 Reg.Year: 2017

Third Party Insurer: MS FIRST
 Third Party Veh No: SHB2179A
 Date of Accident: 04.06.2020

*Not Authorized
 Repair B4 paint*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>B</i> \$967.90 ✓
2	REAR TAILGATE "SHUTTLE" EMBLEM	1		<i>na</i> \$58.50 —
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>na</i> \$74.10 —
4	REAR TAILGATE INNER TRIM CLIPS	8	\$5.60	<i>na</i> \$44.80 X
5	REAR WINDSCREEN RUBBER	1		<i>na</i> \$78.00 ✓
6	REAR BUMPER	1		<i>Pin/na</i> \$783.70 ✓
7	REAR END PANEL	1		REPAIR
SUB TOTAL				\$2,007.00
LESS 20%				-\$401.40
PARTS TOTAL				\$1,605.60

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>na</i> \$60.00 <i>4000</i>
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>na</i> \$30.00 —
S/N TOTAL				\$90.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. \$500.00 *4000*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC. \$600.00 *4000*

LABOUR CHARGES TO REPLACE, REMOVE, REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOUDLING & ETC. TO EFFECT REPLACE OF REAR TAILGATE. \$150.00 *1200*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERTAIONS. \$120.00 *600*

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 08.06.2020
 Vehicle No: SLR8469S
 Model: HONDA SHUTTLE HYBRID 1.5A
 Chassis: GP71116133-2017
 Reg.Year: 2017

Third Party Insurer: MS FIRST
 Third Party Veh No: SHB2179A
 Date of Accident: 04.06.2020

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC. TO
 EFFECT REPLACE OF REAR BUMPER.

\$100.00 50¢

LABOUR CHARGES TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.

\$80.00 20¢

LABOUR TOTAL \$1,550.00

TingAn

TOTAL \$3,245.60

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	082C
Vehicle Details	
Vehicle No.:	SLR8469S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Jun 2020
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	LEB6319994
Chassis No.:	GP71116133
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$20,834.00
Original Registration Date:	29 Aug 2017
First Registration Date:	29 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	28 Aug 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$36,129.00
Total Rebate Amount:	\$39,879.00

The information contained herein is correct as at 06 Jun 2020

OK