

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Abdul Aziz Bin Turru

Accident Date : 05-Mar-20

Vehicle No : FBP5609D

Vehicle Model : Yamaha
Sniper T150

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube-assy	\$ Sec 640.00 X
1	Horn cover inner	\$ 11 80.00 X
1	Front wheel rim	\$ 11 280.00 X
1	Fork under bracket	\$ 11 185.00 X
1	Front rim shaft	\$ 11 45.00 X
1	Front rim bearing	\$ 11 38.00 X
1	Front brake disc	\$ 11 155.00 X
1	Handle bar	\$ Sec 88.00 X
1	Handle bar end - R/H	\$ 11 32.00 X
1	Hand grip (1 set)	\$ 11 55.00 X
1	Handle bar inner bracket	\$ 11 68.00 X
2	Side mirrors	\$ 1/Sec 110.00 X
1	Brake lever	\$ Sec 32.00 ✓
1	Fairing assy (1 set)	\$ Sec 495.00 X
1	Front footrest bracket - R/H	\$ 11 65.00 ✓
1	Brake pedal	\$ 11 35.00 ✓
1	Rear footrest - R/H	\$ 11 42.00 ✓
1	Rear footrest bracket	\$ Sec 40.00 X
1	Exhaust assy	\$ 11 78.00 X
1	Exhaust protector - Rear	\$ Sec 485.00 ✓
1	Exhaust protector - Front	\$ Sec 60.00 ✓
1	Exhaust pipe end cover	\$ Sec 55.00 ✓
	front fairing inner cover 11 65.00 ✓	\$ 3,163.00
	Less 10%	\$ 316.30
		\$ 2,846.70
	<u>Special Net Items</u>	
1	Number plate (1 set)	\$ 11 28.00 X
2	Fork oils	\$ 11 30.00 X
2	Fork oil seals	\$ 11 56.00 X
1	Steering cone (1 set)	\$ 11 90.00 X
1	Rear box	\$ 11 180.00 ✓
1	Rear box bracket	\$ 11 90.00 X
1	Sticket (1 set)	\$ 11 95.00 ✓
		\$ 569.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Abdul Aziz Bin Turru

Accident Date : 05-Mar-20

Vehicle No : FBP5609D

Vehicle Model : Yamaha
Sniper T150

Estimated Repair Costs

S/No.	Labour		
1	To provide towing service	\$ 17	50.00 X
2	To ckeck wiring and reset headlamp focusing	\$ 17	80.00 X
3	To provide labour	\$	380.00 250
4	To repair body frame	\$ 17	350.00 X
		\$	860.00
Grand Total		\$	4,275.70

Singapore Dollars: Four Thousand Two Hundred Seventy-Five and Cents: Seventy only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-487
17
P-438.30
S.N. 395.00
L-250.00
1083.30
201
806