



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

10-06-2020

01-43

TPAXA.

Singapore 417883

Jasper.

MRHFC1660GT000364.

Accident date: 09/06/2020

Estimated repair cost for vehicle no: SMC7098C HONDA CIVIC 1.5 TURBO VTIS '17

CHASSIS: MRHFC1660GT000364

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper Distorted		\$579.50 ✓
2	10	Front Bumper Clip New	\$6.50	\$65.00 30 ✓
3	2	Front Bumper Side Retainer RH Damd	\$25.00	\$50.00 25 ✓
4	1	Front Bumper Reinforcement Bent		\$377.90 ✓
5	1	Front R/H Bumper Fog Lamp Cover torn		\$45.20 ✓
6	1	Front R/H Headlamp Cracked		\$1,299.80 ✓
7	1	Front R/H Headlamp Lower Bracket Cracked.		\$39.00 ✓
8	1	Front R/H Headlamp Top Chrome ut		\$105.80 ✓
9	1	Front R/H Fender Distorted		\$450.80 ✓
10	1	Front R/H Fender Signal Lamp ut		\$36.20 ✓
11	1	Front R/H Fender Cowling torn		\$85.80 ✓
12	6	Front R/H Fender Cowling Clip New	\$6.50	\$39.00 30 ✓
13	1	Front Wiper Tank Deformed.		\$48.90 ✓
14	1	Front R/H Tyre New		\$380.00 ✓
15	1	Front R/H Sport Rim ut		\$1,200.00 600 (SN) ✓
16	1	Front R/H Lower Arm Bent		\$291.40 ✓
17	1	Front R/H Knuckle Arm Damd		\$241.40 ✓
18	1	Front R/H Knuckle Arm Bearing new		\$190.60 ✓
19	1	Front R/H Shock Absorber Bent		\$328.80 ✓
20	1	Front R/H Drive Shaft New		\$1,027.50 X
21	1	Front Steering Rack Bent		\$2,598.80 ✓
Subtotal :-				\$9,481.40

636370 S.N: 600
5090.56

Labour charges

To remove & refit front undercarriage & steering rack

~~\$450.00~~ 320

To check wiring

~~\$100.00~~ 30

Towing fee

~~\$150.00~~ 60

Tuff kote

~~\$150.00~~ X

Panel beating

~~\$1,000.00~~ 700

Spray painting

~~\$1,200.00~~ 800

Subtotal :- \$3,050.00

Total:- \$12,531.40

Supplementary: 275 84.

total 7876 80

4/s 6.3K.

06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

~~54K~~
63K.



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

10/06/2020

Accident date: 09/06/2020

Estimated repair cost for vehicle no: SMC7098C HONDA CIVIC 1.5 TURBO VTIS '17

CHASSIS: MRHFC1660GT000364

S/n	Qty	Items	U/price	Amount
1	1	Front Grille <i>Assembled</i>		\$181.50 ✓
2	1	Front Grille Chrome <i>Not</i>		\$193.20 +
3	1	Front Grille Emblem Logo <i>Not</i>		\$27.40 ✓
4	6	Front Grille Clip <i>Not</i>	\$6.50	\$39.00 20
5	1	Front Turbo Intercooler Pipe <i>Not Not</i>		\$180.00 X
6	1	Front Chassis Bracket <i>Repis</i>		\$220.00 X.
7	1	Front Fender Bracket <i>Best</i>		\$110.00 55
8	1	Front Airbag Sensor Assy <i>Not</i>		\$275.00 X
9	1	Wiper Tank Motor <i>Assembled</i>	80.90 ✓	
Total:-				\$1,226.10

344.80

275.84

CASH SALE/WORK ORDER

YS TOWING PTE LTD

BLK 4015 ANG MO KIO INDUSTRIAL PARK A #01-502, SINGAPORE 569831

TEL: 6788 2233 / 6458 8480 FAX: 6288 8480

Company Registration No. 201628973E

24 hours Hotline : 9765 2992

No 21719

Date, 9/6/20

實號

Messrs:

車號

Vehicle No:

SMC 7098 C

車型

Model No:

Honda Civic

由

From:

時間 (日/夜)

Time (day/night):

其他

Others:

AMC

To:

Autobay


CASH \$:

604

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misadventure to your vehicle whilst being towed. ERP Fees, Car park fees, Cancellation of job and other miscellaneous charges incurred while performing these services shall be borne by the customer.

經手人

Authorised by:



收貨人

Received by: