

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20006189/KPS3Q2

Date: 15/10/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2020-00002180

Claimant
Vehicle No : SMP9290G **Insured Vehicle No :** SJC5705H

Date of Loss: 10/06/2020 Nature of Claim: TP Claim No: 1202000018337

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP9290G	Engine No:	MR20909969B
Make & Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Chassis No:	JN1JANT32Z0002738
Reg. Date:	29/03/2017 (Man. Year: 2016)	Odometer:	58931 km
Colour:	Metallic Pearl White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,554.69	896.87	657.82	42.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	800.00	400.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,754.69	1,696.87	1,057.82	38.40
Approved Total (Overridden) (\$\$)		1,350.00		
(\$\$)	2,754.69	1,350.00	1,404.69	50.99
+ GST 7.00/7.00% (\$\$)	192.83	94.50	98.33	50.99
Nett Amount (\$\$)	2,947.52	1,444.50	1,503.02	50.99
+ Loss of Use (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		1,846.50		
Global Sum Settlement (\$\$)		1,800.00		

INSPECTION

Date of Assignment: 10/06/2020

Date Inspected: 11/06/2020 Inspected At:

City Auto Pte Ltd (HQ)
160 Sin Ming Drive #05-01., Sin Ming
AutoCity,
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Jul 2020)	
Parts:	N/A	NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP9290G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	623.80 FN	*623.80 FN
2	1		*REAR BUMPER RETAINER LH	Distorted	45.50 FN	*45.50 FN
3	1		*REAR BUMPER REINFORCEMENT	Repair	619.80 FN	*- FN
4	1		*REAR BOOT EMBLEM -X-TRAIL	Necessary	105.00 FN	*105.00 FN
5	1		*REVERSE SENSOR	Torn	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	1,694.10	974.30
- Nett Item Discount on N Items 10.00/10.00% (S\$)	139.41	77.43
Total Parts (S\$)	1,554.69	896.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	450.00	360.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	750.00	440.00
Gross Labour Cost (\$\$)			1,200.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >