

(08/11/13) wef

ASS. REC. BY: Marcu

REF:

CCH/A1620006190/11du3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBE 52484
enfa

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

4200

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBE 52484

Yr Regn:

14/5/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha T135

C.C.

135

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

4234

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

54P 302392

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

70-90-17
80-90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Leopard

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

20/5/20

D.O.I.

16/6/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

RL, N/S, S/L
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/6/20 COE 30-4-2025 LTA #2120
4/5 #800 confirmed with mr. Teo.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

☐

Site Insp (\$

) _S + RS_ SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

TOTAL

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Name : Ganasan S/O Balakrishnan

Accident Date : 20-May-20

Vehicle No : FBE5248U

Vehicle Model : Yamaha
T135

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy	\$ 800 640.00 X
1	Front wheel rim	\$ 11 380.00 X
1	Fork under bracket	\$ 11 185.00 X
1	Front rim shaft	\$ 11 45.00 X
1	Front rim bearing	\$ 11 38.00 X
1	Handle bar	\$ 11 88.00 X
1	Hand grip (1 set)	\$ 11 55.00 X
1	Side mirror	\$ cur 55.00
1	Clutch lever	\$ cur 32.00
1	Fairing assy (1 set)	cna/ \$ cur 525.00
1	Front footrest bracket	\$ set 65.00
2	Front footrest rubbers	\$ 70.00
1	Gear pedal	\$ 800 42.00 X
2	Rear footrests	ms \$ cur 80.00 pc
2	Rear footrest brackets	\$ 11 156.00 X
1	Side stand	\$ 75.00 X
1	Main stand	\$ 95.00 X
		\$ 2,626.00
	Less 10%	\$ 262.60
		\$ 2,363.40

Special Net Items

1	Number plste (1 set)	\$ 11 28.00 X
2	Fork oils	\$ 11 30.00 X
2	Fork oil seals	\$ 11 56.00 X
1	Steering cone (1 set)	\$ 11 90.00 X
1	Basket	\$ 11 50.00 X
1	Rear box	\$ cur 120.00
1	E.R.P. IU	\$ 11 175.00 X
1	Front tyre	\$ 11 180.00 X
		\$ 729.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Ganasan S/O Balakrishnan

Accident Date : 20-May-20

Vehicle No : FBE5248U

Vehicle Model : Yamaha
T135

Estimated Repair Costs


S/No. Labour

1	To provide towing service	\$ 17	50.00	X
2	To check wiring and reset headlamp focusing	\$ 12	80.00	X
3	To repair body frame	\$ 12	350.00	X
4	To provide labour	\$	380.00	200
		\$	860.00	

Grand Total

\$ 3,952.40

Dollars: Three Thousand Nine Hundred Fifty-Two and Cents: Forty only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: