

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notified
1/1/2020
Recovery After Paint
9 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 11.06.2020

Accident Date : 10.06.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 额 Amount \$ cts.
Estimate Cost Of Repair To "Toyota Hiace" Reg. No. GBA6589A Claiming Against Your Insured Reg. No. GBA386H			
1pc	Tailgate		
1pc	Tailgate Emblem		
1pc	Tailgate Outer Garnish		
1pc	Tailgate Lock		
1pc	Tailgate Lock Catch ?		
1pc	Tailgate Weatherstrip ?		
1pc	Tailgate Weatherstrip Top Plate ?		
1pc	Tailgate Trim Board		
1pc	Tailgate Trim Board Clips		
1pc	Tailgate Central Locking Device ?		
1pc	Tailgate Glass X		
1pc	Rear Bumper		
10pcs	Rear Bumper Clips		
4pcs	Rear Bumper Brackets		
2pcs	Rear Bumper Corner Retainers LP d/s		
1pc	End Panel		
1pc	End Panel Inner Panel ?		
2pcs	Taillamps X		
2pcs	Taillamp Gaskets X		
1pc	Bonnet		
1pc	Bonnet Emblem		
1pc	Grille		
1pc	Front Bumper		
10pcs	Front Bumper Clips		
1pc	Front Bumper Bracket LH		
1pc	Front Bumper Reinforcement ?		
1pc	Front Bumper Center Air Grille LP X		
1pc	Front Bumper Side Air Grille LP X		
1pc	Front Bumper Tow Cover X		
1pc	Front Bumper Lower Beam ?		
2pcs	Headlamps ?		
1pc	Wiper Tank		
1pc	Air Con Condenser X		
1pc	Radiator X		
	Less 25%		

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be received and is subject to final approval from Insurance Company

Signature: _____
Date: _____

C/F

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 11.06.2020

Accident Date : 10.06.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Hiace" Reg. No. GBA6589A Claiming Against Your Insured Reg. No. GBA386H		
		B/F	-
1pc	Tailgate Glass Sealant	40.00	50.00 SN
1pc	Tailgate Glass Fastener	30.00	50.00 SN
1pc	Tailgate Sticker 70km	12.00	18.00 SN
1pc	Tailgate Sticker 10pax	12.00	18.00 SN
1pc	Tailgate Sticker	60.00	120.00 SN
1pc	Tailgate Trim Board Sticker	50.00	120.00 SN
1pc	Rear Bumper Reverse Sensor	200.00	280.00 SN
1pc	Rear Floor Panel Top Wooden Board	180.00	180.00 SN
1pc	Rear Number Plate	20.00	45.00 SN
1pc	Front Number Plate	20.00	45.00 SN
	To Conduct Electrical Check, Focus Headlamp		30.00 ✓
	To Remove / Refill Air Con Condenser Gas		120.00 X
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00 X
	To Dismantle / Refit Tailgate Fittings / Ancillary Accessories		150.00 60.00
	To Dismantle / Replace Tailgate Glass		160.00 120.00
	To Conduct Rear Electrical Check, Replace reverse Sensors, Module, Rewiring etc.		120.00 50.00
	To Supply Rear Panel Body Sealant		80.00 30.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		150.00 90.00
	To Dismantle / Repair Exhaust Silencer		80.00 X
	Labour Charge - Panel Beating, Repairing Of Support Panel, Headlamp Panel, Rear Cabin Floor Panel, Inner Panel etc. Cnt, Weld Rear End Panel, Inner Panel and Parts Replacement		1,650.00 1000.00
	To Respray Affected Areas		900.00
			1,200.00
		Total :	4,726.00