

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: Z21880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Accident Date: 10.06.2020

Policy No: Third Party

Date: 11.06.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	貨名 DESCRIPTION	單價 Unit Price	總金額 Amount \$ cts.
Estimate Cost Of Repair To "Toyota Hiace" Reg. No. GBA6589A Claiming Against Your Insured Reg. No. GBA386H			
1pc	Tailgate 1942.10		
1pc	Tailgate Emblem		
1pc	Tailgate Outer Garnish		
1pc	Tailgate Lock		
1pc	Tailgate Lock Catch		
1pc	Tailgate Weatherstrip		
1pc	Tailgate Weatherstrip Top Plate		
1pc	Tailgate Trim Board		
1pc	Tailgate Trim Board Clips		
1pc	Tailgate Central Locking Device		
1pc	Tailgate Glass		
1pc	Rear Bumper		
10pcs	Rear Bumper Clips		
4pcs	Rear Bumper Brackets		
2pcs	Rear Bumper Corner Retainers		
1pc	End Panel		
1pc	End Panel Inner Panel		
2pcs	Taillamps		
2pcs	Taillamp Gaskets		
1pc	Bonnet		
1pc	Bonnet Emblem		
1pc	Grille		
1pc	Front Bumper		
10pcs	Front Bumper Clips		
1pc	Front Bumper Bracket LH		
1pc	Front Bumper Reinforcement		
1pc	Front Bumper Center Air Grille LH		
1pc	Front Bumper Side Air Grille LH		
1pc	Front Bumper Tow Cover		
1pc	Front Bumper Lower Beam		
2pcs	Headlamps		
1pc	Wiper Tank		
1pc	Air Con Condenser		
1pc	Radiator		
Less 25%			
LKK Auto Consultants hence notify the Repairer of the following:			
• To survey before/after spray painting			
• To display damaged part(s) during survey			
• Parts prices are subject to confirmation			
• Third party survey is on a "Without Prejudice" basis			
• No illegal modification(s) is allowed			
• Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company			
Acknowledged by Repairer			
Signature:			
Date:			

ASSIGNMENT

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 11.06.2020

Accident Date : 10.06.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	金额 Amount
	Estimate Cost Of Repair To "Toyota Hiace" Reg. No. GBA6589A Claiming Against Your Insured Reg. No. GBA386H		
		B/F	
1pc	Tailgate Glass Sealant		40.00 SN
1pc	Tailgate Glass Fastener		30.00 SN
1pc	Tailgate Sticker 70km		18.00 SN
1pc	Tailgate Sticker 10pax		18.00 SN
1pc	Tailgate Sticker		18.00 SN
1pc	Tailgate Trim Board Sticker		60.00 SN
1pc	Rear Bumper Reverse Sensor		50.00 SN
1pc	Rear Floor Panel Top Wooden Board		200.00 SN
1pc	Rear Number Plate		120.00 SN
1pc	Front Number Plate		80.00 SN
	To Conduct Electrical Check, Focus Headlamp		200.00 SN
	To Remove / Refill Air Con Condenser Gas		30.00 ✓
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		120.00 X
	To Dismantle / Refit Tailgate Fittings / Ancillary Accessories		60.00 X
	To Dismantle / Replace Tailgate Glass		150.00 601
	To Conduct Rear Electrical Check, Replace reverse Sensors, Module, Rewiring etc.		180.00 1201
	To Supply Rear Panel Body Sealant		120.00 501
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		80.00 301
	To Dismantle / Repair Exhaust Silencer		150.00 901
	Labour Charge - Panel Beating, Repairing Of Support Panel, Headlamp Panel, Rear Cabin Floor Panel, Inner Panel etc. Cnt, Weld Rear End Panel, Inner Panel and Parts Replacement		80.00 X
	To Respray Affected Areas		1,650.00 1001
			9001
			1,200.00
	Total :		4,728.00