

ASS. REC. BY:

REF:

CTZ/20006192/Kev

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

820k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBC 1840X

Yr Regn:

OF 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Hiace

c.c

2982

Colour

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

335776

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

K014201 . 0070713

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195 R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

3/6/20

D.O.I.

11/6/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R/P

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/7 21 Day 86700L Cc firm

Date/Time, File Pass to?

☐

: Prel. Report

Days of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 06-Jun-20
DATE OF ACCIDENT : 03-Jun-20
THIRD PARTY REF : GBT 6039 P / China Taiping Ins

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			B	\$ 465.80
1 pc	Rear Bumper Reinforcement			B	\$ 368.70
2 pcs	Rear Bumper Retainer		\$ 45.70	B	\$ 91.40
1 pc	Rear End Panel Outer			B	\$ 269.80
1 pc	Rear End Panel Inner			B	\$ 968.70
1 pc	Rear End Panel Garnish			Bu	\$ 169.80
1 pc	Tailgate			B	\$ 1,950.90
1 pc	Tailgate Lock			Tu	\$ 298.60
1 pc	Tailgate Rubber		210.75	add 10% is	\$ 421.50
1 pc	Tailgate Emblem			B	\$ 68.80
1 pc	Front Bumper			B	\$ 568.10
1 pc	Front Bumper Reinforcement			B	\$ 296.80
1 pc	Front Grille			mtg cm	\$ 451.50
1 pc	Head Lamp LH			bulb wt	\$ 897.40
1 pc	Bonnet			B	\$ 967.44
1 pc	Bonnet Emblem			B	\$ 68.50
					\$ 8,323.74
	Less 25%				\$ 2,080.94
					\$ 6,242.80
1 set	Rear Bumper Sensor	S.Nett		shot	\$ 200.00
2 tubes	Rear Windscreen Sealant	S.Nett	\$ 40.00	B	\$ 80.00
1pc	70km Sticker	S.Nett		B	\$ 15.00
1pc	DHL Logo	S.Nett		(Bill)	\$ 480.00
	To Putty & Spray Paint				\$ 1,000.00
	To transfer Tailgate Fitting				\$ 80.00
	To Remove & Refix Rear Windscreen Glass				\$ 100.00
	To Anti Rust				\$ 80.00
	To check Front Wing & Focus Head Light				\$ 30.00
	Labour Charges				\$ 800.00
TG-TH/-	TOTAL				\$ 9,107.80

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- **Parts prices** are subject to a confirmation
- **Third party** survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

562E

Vehicle Details

Vehicle No.:

GBC1840X

Vehicle to be Exported:

Yes

Intended Deregistration Date:

11 Jun 2020

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE 3.0 DX M

Primary Colour:

White

Manufacturing Year:

2010

Engine No.:

1KD2082463

Chassis No.:

KDH2010070713

Maximum Power Output:

-

Open Market Value:

\$37,390.00

Original Registration Date:

28 Jul 2011

First Registration Date:

28 Jul 2011

Transfer Count:

0

Actual ARF Paid:

\$1,870.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

27 Jul 2021

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$23,900.00

COE Rebate Amount:

\$2,691.00

Total Rebate Amount:

\$2,691.00

The information contained herein is correct as at 11 Jun 2020

OK