

LTM LIM TAN MOTOR

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 06-Jun-20
DATE OF ACCIDENT : 03-Jun-20
THIRD PARTY REF : GBT 6039 P / China Taiping Ins

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			B	\$ 465.80
1 pc	Rear Bumper Reinforcement			B	\$ 368.70
2 pcs	Rear Bumper Retainer		\$ 45.70	m	\$ 91.40
1 pc	Rear End Panel Outer			B	\$ 269.80
1 pc	Rear End Panel Inner			B	\$ 968.70
1 pc	Rear End Panel Garnish			Bu	\$ 169.80
1 pc	Tailgate			B	\$ 1,950.90
1 pc	Tailgate Lock		210.75	Tu	\$ 298.60
1 pc	Tailgate Rubber				\$ 421.50
1 pc	Tailgate Emblem			m	\$ 68.80
1 pc	Front Bumper			m	\$ 568.10
1 pc	Front Bumper Reinforcement			B	\$ 296.80
1 pc	Front Grille			mfg com	\$ 451.50
1 pc	Head Lamp LH			add lwr	\$ 897.40
1 pc	Bonnet			B	\$ 967.44
1 pc	Bonnet Emblem			m	\$ 68.50
					\$ 8,323.74
	Less 25%				\$ 2,080.94
					\$ 6,242.80
1 set	Rear Bumper Sensor	S.Nett		shot	\$ 200.00
2 tubes	Rear Windscreen Sealant	S.Nett	\$ 40.00	m	\$ 80.00
1pc	70km Sticker	S.Nett		m	\$ 15.00
1pc	DHL Logo	S.Nett		(Bill)	\$ 480.00
	To Putty & Spray Paint				\$ 1,000.00
	To transfer Tailgate Fitting				\$ 80.00
	To Remove & Refix Rear Windscreen Glass				\$ 100.00
	To Anti Rust				\$ 80.00
	To check Front Wing & Focus Head Light				\$ 30.00
	Labour Charges				\$ 800.00
TG-TH/-	TOTAL				\$ 9,107.80

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

Acknowledged by Repairer

nature: