

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM20006193/Ags3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE			Date: 02-12-2020 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SFA 4821U	Veh. Inspected	GBJ 2744Y
	Policy No.	GA459808	Coverage (\$)	0.00
	Claim No.	S0M02P2J	Excess (\$)	0.00
	Assign From		Assign Date	11/06/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GDH2011016622	Colour	SILVER
	Odometer	58803	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	10/06/2020	Inspection Date	11/06/2020
	Survey held at	ADVANCE AUTO GARAGE		
	23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days			